


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 **OD** /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s VIN'S MOTOR  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \$750  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \$105k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA /  **REV** / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SNB8713Y Yr Regn: 17 Sep 2021  
 Type  **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HONDA SHUTTLE 1.5G c.c. 1496  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 9632 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GK82103191  
 Gen. Cond:  **Good** / Fair / Poor / Burnt  
 Steering:  **inorder** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  **inorder** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  **Nil** / R/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/60R15  
 R: //  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO /  **YOKO** or \_\_\_\_\_  

<u>Front</u>	<u>Rear</u>
R/Bal. <u>8</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>8</u> mm	L/Bal. <u>8</u> mm
D.O.A. _____	D.O.I. <u>25-03-2022</u>

 Survey held at \_\_\_\_\_ W/S 5:30PM  
 Des. of Damages:  **Frnt** / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	confirmed final fig: \$12,918.50 and 7 days (red,\$1307,0.91%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
02/08/22  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 7  
 Resurvey No. of Trip: 2

Report Fee: \_\_\_\_\_  
 Lump Sum / MP: 12,918.50

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : W/weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
3 + RS. SI	_____
Photos	_____
Other:	_____
TOTAL	_____