

ASS. RES. BY:

REF:

CTH 2200 2785Kpy3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

or

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09

days

Res.: Yes or No

Lum Sum:

10

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX 4866T

Yr Regn:

03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Carens

c.c

1899

Colour

th. Grey

AC:

Insured / Std / NI / NA

Sp. Reading

324351

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAHU815VT7203852

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Continental

DuratunR:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

mm

L/Bal.

8 mm

L/Bal.

mm

D.O.A.

24/3/22

D.O.I.

29/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

11/11/22

14/04/22@2.58pm revised to Jenny Lew via Merimen.

Kenneth finalised LS \$2550, 4 days. (Red \$3200.60, 56%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 14/04 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S - RS, SI

Prints

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum / H.B. / (\$

2550

TOTAL

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

LKK
Kenneth

Not Authorized

11 Sep @ 2550h

Runway After Rain

4 days

ESTIMATION REPORT

Vehicle No : SLX4966T

Make & Model : KIA, Carens EX 1.7 Diesel, KNAHU815VJ7203852

Year of Manufacture : 2018

Estimation No. : E22020003

Date : 25/03/2022

No.	Code	Description	Qty	U/P	Amt
Section: Remark					
1		CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD DOA : 24.03.2022 TP CLAIM (SBL8822E)	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Labour

2		FRONT BUMPER <i>618</i>	<i>Bul/Ref</i> 1.00	618.00	618.00	✓
3		FRONT HEADLAMP RH <i>1450</i>	<i>mgcm 1/m</i> 1.00	1,450.00	1,450.00	✓
4		FRONT HEADLAMP LOWER BRACKET RH	<i>Sn</i> 1.00	21.60	21.60	✗
5		FRONT FENDER RH <i>384</i>	<i>Ry</i> 1.00	384.00	384.00	✓
6		FRONT FENDER INNER COWLING	<i>Dr 1</i> 1.00	68.00	68.00	✓
7		FRONT RIM RH	<i>Sn</i> 1.00	650.00	650.00	✗
8		FRONT BUMPER SIDE RETAINER RH	<i>Dr 1</i> 1.00	14.00	14.00	✓

10?

Amt S\$ 3,205.60
Discount (0.00%) S\$ 0.00
Subtotal S\$ 3,205.60

Section: Special nett

9		FRONT BUMPER CLIPS	6.00	5.00	<i>me</i> 30.00	✓
10		FRONT FENDER INNER COWLING CLIPS	5.00	5.00	<i>me</i> 25.00	✓

Amt S\$ 55.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 55.00

Section: Labour

11		TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, FRONT BUMPER, FRONT FENDER RH AND DAMAGE AREA	1.00	800.00	800.00	<i>400d</i>
----	--	---	------	--------	--------	-------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Continue on next page...

Acknowledged by Repairer

Signature:

Munich Autocare Pte Ltd

62 Jalan Lim Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6265 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SLX4966T

Make & Model : KIA, Carens EX 1.7 Diesel, KNAHU815VJ7203852

Year of Manufacture : 2018

Estimation No. : E22020003

Date : 25/03/2022

No.	Code	Description	Qty	U/P	Amt
12		TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	1.00	120.00	120.00
13		TO CHECK ALL WIRING FOR OPERATION	1.00	150.00	150.00
14		TO APPLY RUST-PROOFING ON AFFECTED AREA	1.00	200.00	200.00
15		TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT	1.00	120.00	120.00
16		TO REMOVE AND REFIX FRONT TYRE TO NEW RIM	1.00	100.00	100.00
17		TO RESPRAY FRONT PORTION, FRONT BUMPER, FRONT FENDER RH AND POLISH DAMAGE AREAS	1.00	1,000.00	1,000.00

Amt S\$ 2,490.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 2,490.00

7301
301
X
X
4401

Remarks:

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

DOA : 24.03.2022

TP CLAIM (SBL8822E)

Total

S\$ 5,750.60

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/03/2022 09:55 (SGT)
Date of Accident 24/03/2022 15:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information CARPENTER STREET
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLX4966T
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner BIS MOTORING PTE LTD
Company Reg No 2XXXXX055D
Email Address KEIFTAN@BISMOTORING.COM.SG
Mobile Phone No (Phone) +65-86881311
Alternative Phone No +65-86881311

VEHICLE PARTICULARS


Manufacturer Kia
Model Carens
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1699

INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number COI-SPMF1000000413-SLX4966T
Cover Note Number -

DRIVER

Name of Driver G SELVARAJ S/O N GANAPATHY PILLAI
NRIC No SXXXX739F



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/3/22 @ 3.45 PM after I turn in Carpenter Street, Suddenly Vehicle B turn out from minor Road on my right side and hit my front Right side of my vehicle. We exchanged particular. No injured

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: