

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/03/2022


User ID : angbangkien

Section A - Accident Details

Registration Number	SHC4749L
Case Reference Number	TAX03/22/2050
Registration Date	12/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	DORAY ANTONIO RAJA
Type of Accident	Head to Rear
Accident Date and Time	24/3/2022 2:30 PM
Accident Reported Date and Time	24/3/2022 3:36 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24114363
Special Instruction to ARC, if any	TP/ REAR PORTION
Prepared Date and Time	24/3/2022 5:11 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,534.30	\$429.82
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$3,148.30 4054.50	\$629.82
Lump Sum Total	\$2,750.00	\$750.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Rasul
ARC / Surveyor Sign Off Date	24/03/2022 5:24 PM	25/03/2022 3:54 PM
Signature		
Remarks		LUMP SUM REPAIR / RESURVEY AFTER REPAIR

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 6365592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/03/2022

User ID : angbangklien

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
O REPAIR REAR PORTION	\$676.00	\$200.00 ✓
total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
O RESPRAY REAR PANEL	\$180.00	\$0.00 X
total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
O WASH AND VACUUM	\$60.00	\$0.00 X
O TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00 X
O REPLACE SUNDRY PARTS	\$100.00	\$0.00 X
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00 X
total Other Costs	\$380.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair R
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given X
		5246247030	PAD, RR BUMPER, RH & LH, 1	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
		5246247020	PAD, RR BUMPER, RH & LH, 2	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
		5246247010	PAD, RR BUMPER, RH & LH, 3	0.00	\$3.80	0.00	\$0.00	Replace	Not Given X
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.20	0.00	\$0.00	Replace	Not Given X
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given X
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given X
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given X
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given X
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given X
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.72	Replace	Replace sue
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace mis
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X
		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given X
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given X
total					\$2,440.50		\$429.82		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
total									

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: