

ASS. REC. BY:

REF:

CS/CTI 22002813/RV y3

1202

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GY9500A

at Workshop m/s BORNO MOTOR

of 2 BORNO CREW

Insured: CTI

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

65K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GY9500A

Yr Regn:

2018 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA HIACE VANTRABO SAR C.C. 2982

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

114616

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFH702P 700245552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15

R:

2"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/03/22

D.O.I.

08/04/22

Survey held at

BORNO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 46K

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

Report Format:



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188


ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Tak Products & Services Pte Ltd 41 Sungei Kadut Avenue Singapore 729665 Mobile: 88208025 <i>小青 6411253</i>		
			Document No.				
			0				
			Document Date				
			22/03/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	KDH201R	SBMDY S5	25/10/2018	GY9500A	0	14007	65DS/GY9500A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700245552	1KD2827794	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : <i>China Taiping.</i> T/P VEH. : SMV1067G ACC DATE : 21.03.22 BY :				100.00 <i>50</i>
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00 ✓
3	S	BP-SUBLET RESET AND REPROGRAMME ECU.				180.00 ✓
4	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				180.00 ✓
5	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				180.00 ✓
6	B	BP-LAB2 REMOVE TAIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				328.00 ✓
7	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS TO <i>plate?</i> ASSIST REPAIR.				450.00 ✓
8	S	BP-SUBLET REMOVE BOOT INTERIOR UPHOLSTERY TO ASSIST REPAIR.				<i>360</i> 720.00 ✓
9	S	BP-SUBLET INSTALL TAIL-GATE COMPANY LOGO.				? 400.00 ✓
10	Z	BP-SUNDRY SUPPLY AND INSTALL 70KM.H AND 5 PAX <i>sticker</i> STICKER.				30.00 ✓

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle 	Parts	Less Amount Due
			Labour	
			Sublet	
		Lubrication/Fluid		
		Others		

Customer Copy



Borneo Motors



TOYOTA

ichcape

No. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurers Company

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Acknowledged by Repairer M/S Tak Products & Services Pte Ltd Signature: 41 Sungei Kadut Avenue Date: Singapore 729665 Mobile: 88208025
	Document No. 0	
	Document Date 22/03/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	KDH201R	SBMDY S5	25/10/2018	GY9500A	0	14007	65DS/GY9500A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTFHT02P700245552	1KD2827794	60	Francis Cher T S	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN TAIL-GATE, TAIL-LAMP PANEL, REAR BUMPER, FLOOR PANEL AND AFFECTED PORTION OF CAR. @720				3600 4320.00
12	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. @520				1770 2950.00
13	1	T52159-26470 REAR BUMPER COVER, de	1.00	481.80		481.80
14	2	T58385-26070 REAR BUMPER BRACKET, ?	3.00	27.70		83.10
15	3	T52158-26010 L/R SIDE BPR RETAINER, ?	1.00	24.80		24.80
16	4	T52157-26010 R/R SIDE BPR RETAINER, ?	1.00	24.80		24.80
17	5	T57069-26120 REAR OUTER FLR MEMBER, bt	1.00	363.70		363.70
18	6	T57068-26320 REAR INNER FLR MEMBER, bt	1.00	1172.50		1172.50
19	7	T67005-26L50 REAR BACK DOOR PANEL bt	1.00	2293.20		2293.20
20	8	T68105-26151 GLASS SUB-ASSY, BACK na	1.00	1419.80		1419.80
21	9	T90975-02064 EMBLEM, SYMBOL na	1.00	72.20		72.20
22	0	T75441-26281 "TOYOTA HIACE" EMBLEM, Brea	1.00	51.60		51.60
23	1	T67935-26190 PLATE, BACK DOOR bt	1.00	112.30		112.30
24	2	TREVSE-FMS02 ZGE 2 PT SENSOR FOR HIACE nw	1.00	56.40		56.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts 6,156.20 Labour 8,638.00 Sublet 1,300.00 Lubrication/Fluid 0.00 Others 0.00	16,094.20
		GST 7.00% 1,126.59 Less 0.00 Amount Due 17,220.79	

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/03/2022 17:01 (SGT)
Date of Accident	21/03/2022 11:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SUNGEI KADUT AVE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY9500A
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TAK PRODUCTS & SERVICES PTE LTD
Company Reg No	1XXXXX120Z
Email Address	WEEMING@TAK.COM.SG
Mobile Phone No	(Phone) +65-98263456
Alternative Phone No	(Home) +65-98263456

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	3000

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D119MFL0000018
Cover Note Number	-

DRIVER

Name of Driver	TAN MUI HONG
NRIC No	SXXXX026F

Date Of Birth	24/07/1957
Occupation	Outdoor
Date Of Driving Pass	27/10/1977
Driving experience	44 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98263456
Alt. Phone Number	-
Email Address	WEEMING@TAK.COM.SG
Address	BLK 498H TAMPINES ST 45 #03-450
Address complement	-
Postcode	526498
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMV1067G
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ANDY WONG
Contact Number	(Phone) +65-90588809
Address	-
Address complement	-

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.





Policyholder's Signature / Date & Time

 21/03/22
Driver's Signature (If driver is not the policyholder) / Date & Time
4.20pm


Francis Chai
Motor Claims Assessor
Borneo Motors (S) Pte Ltd
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

my car was stopped at the traffic lights for about few mins, suddenly vehicle smv 10676 bang my car from behind.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Francis Cher
Motor Claims Assessor
Borneo Motors (S) Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	120Z
Vehicle No.:	GY9500A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2827794
Chassis No.:	JTFHT02P700245552
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	25 Oct 2018
First Registration Date:	25 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	24 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,501.00
COE Rebate Amount:	\$18,625.00
Total Rebate Amount:	\$18,625.00

The information contained herein is correct as at 11 Apr 2022

OK

Toyota Hiace 3.0M

Overview

Financial

Accessories

Similar

Research

Photos

Map



**YOUR ONE-STOP COMMERCIAL VEHICLE
SOLUTION PROVIDER**

Price	\$65,800	Lifespan	28-Oct-2038
Depreciation	\$10,040 /yr View models with similar depre	Reg Date	29-Oct-2018 (6yrs 6mths 17days COE left)
Mileage	N.A.	Manufactured	2018
Road Tax	N.A.	Transmission	Manual
Dereg Value	\$19,333 as of today (change)	Fuel Type	Diesel
COE	\$29,501	OMV	\$28,136
Engine Cap	2,982 cc	ARF	\$1,407
Curb Weight	1,700 kg	No. of Owners	1