



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM22002815/Uea3q2 Date: 07/07/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMA 1350Z	Veh. Inspected	SLV 1741E
	Policy No.	GA539629	Coverage (\$)	0.00
	Claim No.	S2M03WVH	Excess (\$)	0.00
	Assign From		Assign Date	28/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA GRACE DX-HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	GM41109821	Colour	WHITE
	Odometer	94710 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	GITI	6 mm
	L/H Front Tyre	185/60 R15	GITI	6 mm
	R/H Rear Tyre	185/60 R15	GITI	6 mm
	L/H Rear Tyre	185/60 R15	GITI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	25/03/2022	Inspection Date	28/03/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	