



Claim	S2M03WH0
Reference	CS3/ASM22002820/Uvy3e2 
Loss Date	21 March 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	23 Mar 2022 9:34:15 AM
Request Date	28 March 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SLP8598M

Vehicle

Registration #

Make

TPVD-

Model

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE, 575717, Singapore

65551188

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

▼

▼

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Other	Other	do not reply	
 ASM-LKKInvoice-AC2202114.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2022

FAQ

English (SG) ▾

Elaine Kuan ▾

Home

Service Requests

...

ts & Statement

Survey Report

LKK AUTO CONSULTANTS PTE LTD (TP)

13 April 2022

			SUBTYPE	AUTHOR	DATE UPLOADED
 SLP 8598M RES 2_compressed.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 April 2022	
 SLP 8598M IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	7 April 2022	
 SLP 8598M LKKPhotos_compressed.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 April 2022	
 SLP 8598M RES 1_compressed.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 April 2022	
 TP GIA REPORT.pdf.PDF	Reports & Statement	GIA Report	LOH Cynthia	28 March 2022	
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL, Akash	28 March 2022	

FAQ English (SG) ▾ Elaine Kuan ▾			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	...	ts & Statement	GIA Report	PODUVAL, Akash	28 March 2022
 SJ04223M0004-SHA1056H.pdf.pdf			Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	23 March 2022