



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002842/Aty3n2	
			Date: 14/06/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 8685G	Veh. Inspected	SJY 7531M
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201017/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	28/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	ZGE200009192	Colour	GREY
	Odometer	162988 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/03/2022	Inspection Date	28/03/2022
	Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	