

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI22002844/Evy3e2	
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877	Date:	25/07/2022	
			Code	: FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 9087J	Veh. Inspected	GBL 7220Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D22000808MFCV	Excess (\$)	0.00	
	Assign From	JOANNE TAN	Assign Date	28/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	CITROEN ELECTRIC DISPATCH	c.c	0	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	VF7V1ZKXZMZ117098	Colour	WHITE	
	Odometer	4716 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/65 R16C	MICHELIN	5 mm	
	L/H Front Tyre	215/65 R16C	MICHELIN	5 mm	
	R/H Rear Tyre	215/65 R16C	MICHELIN	5 mm	
	L/H Rear Tyre	215/65 R16C	MICHELIN	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/03/2022	Inspection Date	25/04/2022	
	Survey held at	CYCLE & CARRIAGE FRANCE	PTE LTD		
		209 PANDAN GARDENS SINGAPORE 609339			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				
	<u> </u>				