



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22002845/Any3q2 Date: 23/11/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMD 3698S	Veh. Inspected	SMY 6361H
Policy No.		Coverage (\$)	0.00
Claim No.	C10014405/JM	Excess (\$)	0.00
Assign From	SHAFAWATI MD RABU	Assign Date	28/03/2022
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 116D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA1V720605C06809	Colour	SILVER
Odometer	99454 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	MICHELIN	6 mm
L/H Front Tyre	225/40 R18	MICHELIN	6 mm
R/H Rear Tyre	225/40 R18	MICHELIN	6 mm
L/H Rear Tyre	225/40 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/03/2022	Inspection Date	30/03/2022
Survey held at	ACE AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	