



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN KHONG			Ref: CC4/ASM22002848/Uea3q2 Date: 13/06/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3237D	Veh. Inspected	SMN 5372R	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M03WW8	Excess (\$)	0.00	
Assign From		Assign Date	28/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO 1.6 EX (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KNAF3416MK5045850	Colour	BLACK	
Odometer	43166 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	8 mm	
L/H Front Tyre	205/55 R16	MICHELIN	8 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2022	Inspection Date	28/03/2022	
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	