

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22002868/Gvy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 06/04/2022 SINGAPORE 068811 ATTN: KHONG LYNN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 2203T** SLP 2360X Veh. Inspected Policy No. VFX/P2465679 Coverage (\$) 0.00 Claim No. S2M03WZ5 Excess (\$) 0.00 **Assign Date** KHONG LYNN 29/03/2022 Assign From **Vehicle Particulars & Condition** 2. MITSUBISHI LANCER EX 1.6 c.c Make & Model 1590 HIDDEN 2017 Engine No. Year of Reg. JMYSRCY1AGU007014 Chassis No. Colour **GREY** 111073 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 205/60 R16 **TOURADOR** 6 mm **TOURADOR** L/H Front Tyre 205/60 R16 6 mm 205/60 R16 **TOURADOR** R/H Rear Tyre 6 mm **TOURADOR** L/H Rear Tyre 205/60 R16 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. 5. **General Information** 18/03/2022 29/03/2022 (04:00 PM) Inspect Date / Time Accident Date 55 SERANGOON NORTH AVE 4 #02-10 S (555859) Survey held at 1 STOP GARAGE PTE. LTD. Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/ASM22002868/Gvy3e2

Estimate Days of Repair

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days

Automotive Assessor