

ASS. REC. BY:

T. Lim

REF:

CC6/AIC22002869/Bga3

Coelia

ASSIGNMENT

From:

Date:

30/3/2022

Estimated Cost:

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SLW 1373D

at Workshop m/s

Jean Auto pro

of 160 Sin Ming Dr # 01-14

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

121,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 1373D

Yr Regn: 30/1/2018

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz CLA 180

c.c 1595

Colour:

Green

A/C: Insured / Std / NI / NA

Sp. Reading

73053

T/Radio: Insured / Std / NI / NA

Eng/No:

27091031507557

C/No:

WDD1173422A607642

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: Nil / ☒ STD A/Rim or

Tyre Size:

F: 235/35/19

Falken

R: 235/35/19

Pirelli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

28/3/2022

D.O.I.

30/3/2022

Survey held at

Jean Auto pro

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: 5000/- - 6000/-

Recommended CR: LS \$5850.00

MV 121,000/-

PV 49,375/-

NV 71,625/-

T. Lim

30/3/2022

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Rep. Format:

Lump Sum / L.B. / C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SLW 1373 D**
 Model : Mercedes CLA250
 Year : 2018
 Chassis No : WDD1173422N607642

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 1,987.90	\$ 1875.00 1,987.90
2	Bootlid logo	1	\$ 110.00	\$ 68.00 110.00
3	Bootlid emblem 'CLA250'	1	\$ 148.00	\$ 87.00 148.00
4	Bootlid weather strip	1	\$ 468.00	\$ 468.00
5	Bootlid inner lock assy	1	\$ 574.00	\$ 574.00
6	Bootlid outer garnish	1	\$ 382.60	\$ 382.60
7	Rear bumper	1	\$ 1,886.00	\$ 1438.00 1,886.00
8	Rear bumper lower	1	\$ 686.30	\$ 368.00 686.30
9	Rear bumper lower center garnish	1	\$ 275.30	\$ ✓ 275.30
10	Rear bumper reinforcement	1	\$ 698.00	\$ 480.00 698.00
11	Rear bumper centre beam garnish	1	\$ 213.90	\$ 213.90
12	Rear bumper reverse sensor	2	\$ 145.00 265.00	\$ 290.00 1,590.00
13	Rear bumper heat shield	1	\$ 288.00	\$ 288.00
14	Rear bumper tow cap	1	\$ 125.00	\$ 125.00
15	Rear end panel outer	1	\$ 1,125.00	\$ 980.00 1,125.00
16	Rear end panel inner	1	\$ 995.00	\$ 995.00
17	Rear end panel top garnish	1	\$ 415.00	\$ 415.00
18	Taillamp	2	\$ 730.00	\$ 1,460.00
19	Taillamp bracket	2	\$ 109.00	\$ 218.00
20	Rear exhaust pipe chrome tip	2	\$ 345.00	\$ 690.00
21	Rear exhaust pipe heat shield	1	\$ 181.60	\$ 181.60
			Parts Sub Total :	\$ 5861.30 14,517.60
			Discount :	\$ 386.13 1,451.76
			PARTS TOTAL :	\$ 13,065.84

10%

5275.17

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bootlid sealant	1	\$ 100.00	\$ 100.00 30.00
3	Bootlid inner trim board clips	1	\$ 60.00	\$ 60.00 30.00
4	Rear bumper clips	1	\$ 60.00	\$ 60.00 30.00
5	Rear bumper lower clips	1	\$ 60.00	\$ 60.00 30.00
6	Rear bumper side retainer	2	\$ 48.00 156.00	\$ 312.00 96.00
7	Rear bumper reverse sensor seal	6	\$ 58.00 25.50	\$ 348.00 153.00
8	Rear end panel sealant	1	\$ 100.00	\$ 100.00 30.00
9	Rear end panel top garnish clips	1	\$ 60.00	\$ 60.00
10	Taillamp clips	2	\$ 60.00	\$ 120.00
11	Taillamp seal	2	\$ 60.00	\$ 120.00
SPECIAL NETT TOTAL :				\$ 1,420.00

399.00

Nos.	LABOUR	S\$
1	R&R Bootlid component	\$ 150.00 80.00
2	R&R rear bumper reverse sensor	\$ 100.00 60.00
3	Diagnostic reset fault code	\$ 300.00 120.00
4	Check wiring	\$ 100.00
5	Upholsterty	\$ 300.00
6	Panel beating	\$ 1,600.00 800.00
7	Rust proofing	\$ 200.00
8	Spray painting	\$ 1,600.00 600.00
LABOUR TOTAL :		\$ 4,350.00

1660.00

PARTS TOTAL : \$ 13,065.84
SPECIAL NETT TOTAL : \$ 1,420.00
LABOUR TOTAL : \$ 4,350.00
GRAND TOTAL : \$ 18,835.84

Survey 30/3/2022 1430 hrs TGL in line
Resurvey 31/3/2022 1330 hrs TGL in line

Parts 5,275.17
SN 399.00
Labour 1660.00
7,334.17
@ 20 % 1466.83
5867.34

LS 5,850.12

TGL in line
30/3/2022

Lump sum repair
Repair days: 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Prepared by Eric (8269-9999) Page 2 of 2

Date:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	ACQ	Q
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SC	✓	2
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NG	✓	2
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SLW 1373D

NAC	INC	Item	CON	ACQ	Q
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Rear bumper inner centre			
		garnish	BR	✓	

No of Items: 8

Assessor: JGhim

30/3/2022

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	910C
Vehicle Details	
Vehicle No.:	SLW1373D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Mar 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 AMG LINE AUTO
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	27091031507557
Chassis No.:	WDD1173422N607642
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$32,244.00
Original Registration Date:	30 Jan 2018
First Registration Date:	30 Jan 2018
Transfer Count:	1
Actual ARF Paid:	\$37,142.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jan 2028
PARF Rebate Amount:	\$27,856.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$21,519.00
Total Rebate Amount:	\$49,375.00

The information contained herein is correct as at 29 Mar 2022

OK

MV 121,000/2
PV 49,375/2
NV 71,625/2

TG in line
30/3/2022

Send/Fax to: _____

Submitted: _____

SINGAPORE ACCIDENT STATEMENT

BASIC INFORMATION			
Date of Accident:	28/03/2022	Time of Accident:	16:00
Exact Location:	PIE Towards Changi Before Toh Guan Exit		

DETAILS OF OWN VEHICLE			
Vehicle Registration No.	SLW 1373 D	NRIC / FIN / Passport no:	S9021910C
Name of Registered Owner:	TENG ZHI YING		
Owner's Email:	junlong2308@hotmail.com		
Owner's Address:	BLK 899C Woodlands Drive 50 #08-288 Singapore 732899		
Vehicle Make:	Mercedes	Vehicle Model:	CLA 180
Engine Capacity (cc):	1595 cc	Transmission:	Auto / Manual
Type of Claim:	Own Damage / Third Party / Reporting Only		
Vehicle Category:	Private / Commercial / Motorcycle / Private Hire		
Name of Insurance Co:	NTUC		
Type of Policy:	Comprehensive / Third Party / Third Party, Fire & Theft		
Policy Number:	5123083531		

DRIVER			
Name of Driver:	ONG CHUN LONG	<input type="checkbox"/>	same as
NRIC / FIN / Passport no:	S8830415B	Date of Birth:	23/08/1988
Occupation:	Indoor / Outdoor	Driving Pass Date:	07/04/2015
Contact Number:	8031-2323	Gender:	Male / Female
Address:	Blk 120 Ho Ching Road #01-97 Singapore 610120		
Relationship with Owner:	Owner / Employee / Spouse / Child / Hirer / Other:		

GENERAL INFORMATION OF THE ACCIDENT			
Type of Collision:	Chain collision / Side Swipe / Front to Rear / Others:		
Weather Condition:	Clear / Raining / Others: Drizzling		
Road Surface:	Dry / Wet / Others:		
Was anybody injured?	Yes / No	Police Report Made?	Yes / No
No. of passenger onboard (including driver):	1		

DETAILS OF OTHER VEHICLE			
	Vehicle 1	Vehicle 2	Vehicle 3
Vehicle Registration No:	GBF 5269 D		
Vehicle Make / Model:			
Name of Driver:	Terry Giam Yang Li		
NRIC / FIN / Passport no:	S9404250Z		
Contact Number:	933744560		
Name of Insurance Co:			

DETAILS OF WITNESS	
Name:	Contact Info:

DETAILS OF INJURED PERSON			
	Person 1	Person 2	Person 3
Name / in which vehicle?:	ONG CHUN LONG SLW 1373 D		

Driver's Declaration: I declare that the information given in this report are true and accurate to the best of my collection and I bear full responsibility for any consequences arising from incomplete or inaccurate information that are submitted.

Signature of Driver: _____

Date and time: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident; (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Sketch Plan diagram showing vehicle positions and directions. The diagram includes a vertical line with arrows indicating movement. To the left of the line, the text "P16 Towards Changi" and "Rajade Teh Guan EXIT" is written. To the right of the line, the text "Veh A : SLW 1373 D" and "Veh B : GBF 5269 D" is written. The diagram also shows a series of boxes containing the letters A and B, indicating the positions of the vehicles.


Describe Circumstances of the Accident

Refer to Police Report
7/2022 0329/7017

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



SINGAPORE POLICE FORCE



T/20220329/7017

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20220329/7017

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/03/2022 12:48		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ONG CHUN LONG			Address: 120 HO CHING ROAD #01-97 SINGAPORE 610120		
ID Type / ID No.: NRIC NO / S8830415B			Contact No.: Home/Office: Mobile: 80312323		
Nationality: SINGAPORE CITIZEN			Email: junlong2308@hotmail.com		
Sex: Male	Age: 33	Date of Birth: 23/08/1988	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 28/03/2022 16:00	Type of Location: Straight Road
Location: PAN ISLAND EXPRESSWAY TOWARDS CHANGI BEFORE TOH GUAN EXIT				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
GBF5269D	Van					0
SLW1373D	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20220329/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20220329/7017

CONTINUATION OF REPORT

Driver				
Name	TERRY GIAM YANG LI		ID No.	S9404250Z
Related Vehicle	GBF5269D (Van)		Contact No.	93374560
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL
Driver				
Name	ONG CHUN LONG		ID No.	S8830415B
Related Vehicle	SLW1373D (Car)		Contact No.	80312323
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	28/03/2022		Date	NIL
No. of Days granted Medical Leave	05		Degree of	Slight

Brief Details.

On the stated date and time, I (SLW 1373 D) was travelling along the sated venue. It was drizzling and the road surface was wet. As I saw front vehicles braked to stop, I followed to brake to stop too. When I have come to a complete halt, suddenly a vehicle bearing registration no: GBF 5269 D could not stop in time and collided onto the rear of my vehicle. The impact was huge and also caused my vehicle to move forward. I felt unwell and discomfort on my head and neck after the collision. I then proceeded to seek medical treatments at Mount Alvernia Hospital and was given 5 days MC.



**SINGAPORE
POLICE FORCE**



T/20220329/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20220329/7017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
MUHAMMAD NOOR BIN ABDUL RAHMAN
Contact No.: 65476201

Signature Of Informant:

The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
29/03/2022 12:48

Classification Of Case: