

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305509843
Date : 02.04.22

FINALIZATION FORM

To : LKK
Attn : THEVAN

Fax :

Vehicle Reg No. : SHC8206K Date of Accident : 22.03.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBJ1663D
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$2,057.80
 - (b) Labour Charges (include advertisement stickers etc,if any) \$620.00
 - Total for Part-By-Part Repair Cost \$2,677.80
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 25/04/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305509843

REGN NO : SHC8206K

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : IONIQ(G3)

DATE OF REGN : 16.01.2020

DATE/TIME IN : 22.03.2022 15:45

ACCIDENT DATE : 22.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2687-G	FRT BUMPER UPR MOULDING	1	368.50	20.00	294.80
0002 04-01-0104-2685-G	DAYLIGHT GRILLE LH	1	93.45	20.00	74.76
0003 04-01-0104-2835-G	HEADLAMP LH	1	2,110.30	20.00	1,688.24

SUB-TOTAL : 2,057.80

JOB NATURE

0000 PB	PANEL BEATING	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 17-01	CHECK ALL LIGHTING	20.00

SUB-TOTAL : 620.00

TOTAL : 2,677.80

MVA NAME & SIGNATURE
DATE :AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.03.2022

REPAIR ESTIMATE

China Taiping CP/P)

Time: 08:46:51

Page: 1/2

LKK -

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305509843
REGN NO : SHC8206K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 22.03.2022 15:45
ACCIDENT DATE : 22.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G	FRT BUMPER	1	481.10	20.00	384.88	Xr
0002 04-01-0104-2687-G	FRT BUMPER CTR UPR MOULDING	1	368.50	20.00	294.80	/Scr
0003 04-01-0104-2685-G	DAYLIGHT GRILLE LH	1	93.45	20.00	74.76	/Scr
0004 04-01-0104-2835-G	HEADLAMP LH	1	2,110.30	20.00	1,688.24	/Scr
0005 04-01-0104-4894-G	DAYLIGHT LH	1	642.50	20.00	514.00	XScr

SUB-TOTAL : 2,956.68

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 17-01	CHECK ALL LIGHTING	40.00	20

SUB-TOTAL : 740.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.03.2022

Time: 08:46:51

Page: 2/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305509843
REGN NO : SHC8206K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 22.03.2022 15:4
ACCIDENT DATE : 22.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,696.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thevan
82235769
23/3/22 1630
2 days wp
p/p repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: