Insp By: Thevan | Ref: CTI

ASSIGNMENT

Date:

Estimated Cost

TP / WS / TP RES / CD RES / EVA / UNV / MV

Insurance Veh No:

Workshop nv:

Excess:

Record:

Veh:

Condition:

The veh had commenced its repair at the time of inspection.

N/S | O/S

or Market Value:

Accident Rpt: Consistent? : Yes or No

PR Seen: Consistent? : Yes or No

Repair: 2 days Res.: Yes or No

Dmt: % 3 Val.: Yes or No

REV / REP. / 24 HRS

Person Contacted: Vehicle: IN / OUT

Veh No: SHC8206K Yr Regn: 16/1/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover / Truck / Trailer or

Make: Hyundai Ioniq cc: 1580

Colour: blue A/C: , Insured / Std / Nil / NA

Sp.Reading: 200454 T/Radio: Insured / Std / Nil / NA

Eng/No

C/No: KMHC851CULU188961

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / (S/Rim) / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	~~16/1/20~~ 22/3/22	D.O.I.	23/3/22 1630

Survey held at CDOE

Des. of Damages : (Fn) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	no GI provided

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($) [ ] : Interview ($) [ ] : Tech. Inve ($) [ ] : Weekend ($

Survey Fee:

Transportation: __$ * RS __$

Photos

Other

TOTAL

TS

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE China Taiping CP/P)

Date: 23.03.2022
Time: 08:46:51
Page: 1/2

LKK -

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305509843
REGN NO	:	SHC8206K
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	IONIQ(G3)
DATE OF REGN	:	16.01.2020
DATE/TIME IN	:	22.03.2022 15:45
ACCIDENT DATE	:	22.03.2022

JOB / PARTS DESCRIPTION	QTY	IND UNIT-PRICE	DISC%	AMOUNT	
PART REQUISITION					
0001 04-01-0104-0578-G FRT BUMPER	1	481.10	20.00	384.88	XR
0002 04-01-0104-2687-G FRT BUMPER CTR UPR MOULDING	1	368.50	20.00	294.80	SCR
0003 04-01-0104-2685-G DAYLIGHT GRILLE LH	1	93.45	20.00	74.76	SCR
0004 04-01-0104-2835-G HEADLAMP LH	1	2,110.30	20.00	1,688.24	SCR
0005 04-01-0104-4894-G DAYLIGHT LH	1	642.50	20.00	514.00	XSVC

SUB-TOTAL : 2,956.68

JOB NATURE			
0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 17-01	CHECK ALL LIGHTING	40.00	20

SUB-TOTAL : 740.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.03.2022
Time: 08:46:51

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO	:	305509843
REGN NO	:	SHC8206K
MILEAGE	:	0000000000
MAKE	:	HYUNDAI
MODEL	:	IONIQ(G3)
DATE OF REGN	:	16.01.2020
DATE/TIME IN	:	22.03.2022 15:4
ACCIDENT DATE	:	22.03.2022

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT

TOTAL : 3,696.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thevan
82235769
23/3/22 1630
2days wp
P/P repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

COMFORTDELGRO
NGINEERING

ComfortDelGro Engineering Pte Ltd

Date/Time: 23.03.2022 08:21 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4187858 JC NO305509843

OMER

IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

OUNT CARD NO.

REGN NO. SHC8206K	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL IONIQ(G3)	DATE/TIME IN 22.03.2022 15:45
YR OF MANU. 16.01.2020	TARGET DATE
CHASSIS CODE KMHC851CVLU188961	COMPLETION DATE/TIME

JOB DESCRIPTION

ccident Date: 22.03.2022
ATURE: 3P 22.03.2022

NO	LABOR CODE	DESCRIPTION
0010	PB	PANEL BEATING
0020	SP	SPRAYPAINT CHARGE
0030	17-01	CHECK ALL LIGHTING



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

dgement Slip

: SHC8206K LIMTS

ervice Advisor

Signature/Date

ned to Service Reception upon collection

Exit Pass

Vehicle No.: SHC8206K

Name of Service Advisor

Date

To be kept by Security Guard