

李 汽 车 贸 易

ERZAT LEE MOTOR TRADING PTE LTD

Synergy @ KB 25 Kaki Bukit Road 4 #03-37 Singapore 417800

GST Reg: 201918537M

Reg: 201918537M

Email: Enquiry@erzatleemotor.com

Office: 69961751

VEHICLE NO: FBR 3437 K

VEHICLE MODEL: AEROX 155

QUOTATION SUMMARY: 1108

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	Surveyor Recommendation
1	FORK SET ✓ <i>As per local repair</i>	1	\$550.00	\$550.00	150 (SN)
2	FORK T UNDER BRACKET X <i>NN</i>	1	\$400.00	\$400.00	
3	STEERING CONE ✓ <i>REV</i>	1	\$200.00	\$200.00	
4	FRONT TYRES SHAFT X <i>NN</i>	1	\$150.00	\$150.00	
5	HANDLE BAR ✓ <i>BT.</i>	1	\$350.00	\$350.00	
6	HANDLE BAR END ✓ <i>Cut</i>	1	\$100.00	\$100.00	
7	BRAKE LEVER (R) ✓ <i>cut</i>	1	\$120.00	\$120.00	
8	MIRROR SET ✓ <i>cut</i>	1	\$150.00	\$150.00	
9	FRONT SIGNAL LIGHT (R) ✓ <i>BR</i>	1	\$200.00	\$200.00	
10	INNER COVER (R) ✓ <i>cut</i>	1	\$280.00	\$280.00	
11	FRONT FOOTREST COVER ✓ <i>cut</i>	1	\$250.00	\$250.00	
12	FOOTREST UNDER COVER ✓ <i>cut</i>	1	\$180.00	\$180.00	
13	REAR FOOTREST (R) ✓ <i>cut</i>	1	\$150.00	\$150.00	
14	BODY UNDER COVER X <i>NN</i>	1	\$280.00	\$280.00	
15	EXHAUST COVER ✓ <i>cut</i>	1	\$200.00	\$200.00	
16	HEAD LIGHT ✓ <i>cut</i>	1	\$700.00	\$700.00	

17	FRONT MUD GUARD ✓ BR.	1	\$230.00	\$230.00	
18	PANEL COVER ✓ BR.	1	\$200.00	\$200.00	
19	FAIRING COVER ✓ Cat.	1	\$350.00	\$350.00	
20	REAR FAIRING COVER ✓ Cat.	1	\$280.00	\$280.00	
21	LABOUR	1	\$500.00	\$500.00	200.
TOTAL			\$ 5820.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5320.00
TOTAL LABOUR COST : \$ 500.00
TOTAL REPAIR COST : \$ 5820.00

2 Days.
Large repair
After repair photos
Guru Arian
82880282
29/3/22.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: