

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI22002888/Kvy3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 25/04/2022	
			Co	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKZ 9449M	Veh. Inspected	SGU 9128M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10014430/EE	Excess (\$)	0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date	29/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS (A)	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	MR053HY9305001871	Colour	METALLIC SILVER	
	Odometer	308996 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	MICHELIN	8 mm	
	L/H Front Tyre	195/55 R15	MICHELIN	8 mm	
	R/H Rear Tyre	195/55 R15	TRIANGLE	9 mm	
	L/H Rear Tyre	195/55 R15	TRIANGLE	9 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	24/03/2022	Inspection Date	12/04/2022	
	Survey held at 176 SIN MING DRIVE #04-06 SIN MING AUTOCARE				
	Repairer DING AUTO PTE LTD				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
			Days of Repair		

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: