



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002893/Avy3s2	
			Date: 26/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLS 1698M	Veh. Inspected	SKW 6860T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201028/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	29/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SYLPHY	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	MNTBBAB17Z0024967	Colour	RED
	Odometer	92037 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R15	FIRENZA	6 mm
	L/H Front Tyre	205/55 R15	FIRENZA	6 mm
	R/H Rear Tyre	205/55 R15	FIRENZA	6 mm
	L/H Rear Tyre	205/55 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/03/2022	Inspection Date	29/03/2022
	Survey held at	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING		
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	