ASS. REC. BY: STEVE

REF: CS/CTI 22002900/Kgy3

ASSI	GNMENT
From: Date:	Veh No: PC 1165X Yr Regn: 15/11/11
Estimated Cost:	Type: M.Car / M.Cycle (Bus) Van / Lorry / Taxl / Prime Mover /
OD (TP) WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No:	Make: 13474 LT134P c.c 7790
at Workshop m/s	Colour Multicelour AIC: Insured / Std / NI / NA
of	Sp.Reading 504146 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JALLT 34PB 700 0075
Claims No. SNM22D202126/C02	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STO A/Rim or
	Tyre Size: F: 295/80877.5
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of Inspection.	TOYO / YOKO or
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal.
GIA / PR Seen:Consistent? : Yes or No	L/Bal. L/ mm L/Bal. U mm D.O.I. 393/77
Est. Repairs: 18 days Res.; Yes or No	Lord on Mark 2
Lum Sum: % 3 Val.: Yes or No	00170) 11010 01
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	ino dio i dilaccioname i seri
05/04/22@2.48pm revised to Jacqueline Tan v	ia Merimen.
	irmed as wksp didn't accept our offer)
Steve: 14k to 15k per year. MV arour	10 \$58 K
Date/Time, File Pass to? : Prell. Report	Days Of Repair: 18
	Resurvey No. of Trip: 2 Survey Fee:
1)27/05 Typist Final Report Date/Time, File Return to?	Transportation:
Add Fee	: Site Insp (\$)_s+Rs,_si
A second control of the second	: Interview (\$) Photos
Report Format:	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$)	:Weekend (\$)

CONNECTS

566 Woodlands Road (Mandai Estate) Singapore 728697 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Rec: 53360061L WIL PL GST:53360061L Steve (LKK) 30/3/22, 3-997

QUOTATION

QT22/PC1165X/TPC

China Taiping Insurance (Singapore) Pte Ltd 3 Anson Rd #15-02 Springleaf Tower Singapore 079909

Dear Sir,

Cost of Repair to Vehicle PC1165X

With reference to the above-mentioned, we are pleased to quote as follows:-

1	Terefered to the above-mentioned, we are please	d to quot	c as follows.	
No	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (SS)
1.	Rear end panel (11) / 01)	1	2,800.00	2,800.00
2.	Rear end panel grille ('Inny) / 00)	1	3,200.00	3,200.00
3.	Rear LH taillamp / JR	1	1,850.00	1,850.00
4.	Rear LH taillamp panel inner structure / M	1	2,000.00	2,000.00
5.	Rear tailgate () nuv) / DD	1	4,200.00	4,200.00
6.	Rear tailgate inner structure / 00	1	1,800.00	1,800.00
7.	Rear tailgate grille / 00	1	630.00	630.00
8.	Rear tailgate lock X	1	580.00	580.00
9.	Rear tailgate stopper χ	2	235.00	470.00
10.	Rear tailgate hinges / 1/5	4	285.00	1,140.00
11.	Rear tailgate sensor \(\lambda \)	2	350.00	700.00
12.	Rear tailgate gas spring / $\ell \bar{l}$	21	115.00	230.00
13.	Rear tailgate brackets / GT	2	385.00	770.00
14.	Rear LH taillamp panel fibre / DK	1	2,100.00	2,100.00
15.	Rear LH taillamp panel inner structure / 0	1	970,00	970.00

17. Rear LH last piece compartment cover 10	1/				
Rear LH last piece compartment cover		Rear LH side panel / 00	ı	4,800.00	4,800.00
Rear LH last piece compartment cover grille 1		Rear LH last piece compartment cover / 00	1	1,750.00	1,750.00
19 Rear LH last pe compartment gas spring 17 2 185.00 370.00		Rear LH last piece compartment cover grille	00 1	470.00	470.00
Structure Stru	19	The state of the s	CONTRACTOR CONTRACTOR	185.00	370.00
21. Rear pully	20	and pe compartment timer base	7 1	850,00	850.00
Pan bell Pan bell	21		1	1,860.00	1,860.00
Radiator assy 1	22	Fan belt 2 / Th	1	890.00	890.00
Radiator assy base and bracket	23	Radiator assy 1	1	4,650.00	4,650.00
Radiator fan cowling	24	Radiator assy base and bracket	1	1,020.00	1,020.00
27. Sealant	25	Radiator fan cowling ?	1	740.00	740.00
Sealant	26	Radiator fan blades	1	240.00	340.00
29. Reverse sensor / DR	27	Sealant / ML	15	40.00	600.00
1 380.00	28.	60KM/H sticker / /lu	1	15.00	15.00
assist repair 1 1 1 200 500.00 500.00 31. Labour to remove & refit LH side glasses to assist repair 1 1 1 1 1 1 1 1 1	29.	Reverse sensor / OR	1	380.00	380.00
31. Labour to remove & refit LH side glasses to assist repair 1 1600 2,400.00 2,400.00 32. Labour to remove & refit LH side seats, trims, upholstery etc to assist repair 1 600 900.00 900.00 33. Labour to remove rear seats, trims, upholstery etc to assist repair 1 500 600.00 600.00 34. Spray foam 1 300 500.00 500.00 35. Apply anti rust 1 150 200.00 200.00 36. Check wiring 1 50 100.00 100.00 37. Labour charges 1 36004,200.00 4,200.00 38. Spray painting + (chiii) 1 3000 3,600.00 3,600.00	30.		1	WOO 500.00	500.00
32. Labour to remove & refit LH side seats, trims, upholstery etc to assist repair 33. Labour to remove rear seats, trims, upholstery etc to assist repair 34. Spray foam 35. Apply anti rust 36. Check wiring 37. Labour charges 38. Spray painting + (ckspn) 30. O 900.00 900.00 900.00 900.00 900.00 900.00 900.00 900.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00	31.	Labour to remove & refit LH side glasses to	1		2 400 00
trims, upholstery etc to assist repair 33. Labour to remove rear seats, trims, upholstery etc to assist repair 34. Spray foam 35. Apply anti rust 1				1000 2,100.00	2,100.00
34. Spray foam 1 300 500.00 500.00 35. Apply anti rust 1 150 200.00 200.00 36. Check wiring 1 50 100.00 100.00 37. Labour charges 1 3600.00 4,200.00 38. Spray painting + (cksign) 1 3000 3,600.00 3,600.00	32.		1	600 900.00	900.00
34. Spray foam 1 3005000 500.00 35. Apply anti rust 1 1502000 200.00 36. Check wiring 1 501000 100.00 37. Labour charges 1 $36004,200.00$ 4,200.00 38. Spray painting $\frac{1}{2}$ (clssp) 1 $30003,600.00$ 3,600.00	33.		1	500 600.00	600.00
36. Check wiring 1 $50\ 100.00$ 100.00 37. Labour charges 1 $36004,200.00$ 4,200.00 38. Spray painting $+ (cksign)$ 1 $3000\ 3,600.00$	34.		1	300 500.00	500.00
37. Labour charges 1 36004,200.00 4,200.00 38. Spray painting + (cksign) 1 3000 3,600.00 3,600.00	35.	Apply anti rust	1	150 200.00	200.00
37. Labour charges 1 36004,200.00 4,200.00 38. Spray painting + (dsign) 1 3000 3,600.00 3,600.00	36.		1	50 100.00	100.00
38. Spray painting + (cksign) 1 3000 3,600.00 3,600.00	37.		1	36004,200.00	4,200.00
OUD TOTAL	38.		1	3000 3,600.00	3,600.00
5555,175,00				SUB-TOTAL	S\$55,175,00

Price exclude 7%gst

Yours faithfully,

Winnie Chai HP: 9850-9666 LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

SKOL223S000L / KAN FOOK SING MOTOR WORKSHOP [539147] ENTRY DATE & TIME: 28/03/2022 16:37 (SGT) SUBMITTED BY: Boo Miow Hwa VERSION: 1 (28/03/2022 16:37 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

28/03/2022 16:37 (SGT) Date of Submission 28/03/2022 05:20 (SGT) Date of Accident Singapore **Exact Location of Accident PENJURU ROAD**

Additional Location Information Singapore Country/State of Loss

DETAILS OF OWN VEHICLE

PC1165X Vehicle Registration Number

INSURED/POLICYHOLDER

Yes Is company? PREMIERE COACH PTE LTD Name Of Registered Owner 2XXXXX609W Company Reg No admin@premierecoach.com.sg Email Address (Phone) +65-66844622 Mobile Phone No

VEHICLE PARTICULARS

Alternative Phone No

SUZU Manufacturer LT134P Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category Transmission CC

No - Claiming third party Bus

(Office) +65-66844622

Manual 7790

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

NTUC Income Insurance Co-operative Ltd ThirdPartyFireTheft 5119115628-01-000012 21/09/2021 TO 20/09/2022

DRIVER

Name of Driver Work Permit No KYAW HLAING OO GXXXX095K

Accident report SK0L223S000L

Page 1 of 15

Date Of Birth 29/01/1986 Occupation Date Of Driving Pass Outdoor Driving experience 25/01/2021 1 YEAR AND 2 MONTHS Gender Male Mobile Number (Phone) +65-90922932 Alt. Phone Number Email Address admin@premierecoach.com.sg Address 48 YUNNAN WALK 3 SINGAPORE 638179 Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Collision - Head to Rear Type of Accident Clear Weather Conditions Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? PASSENGER 1 **PASSENGER** Name Male Gender PASSENGER 2 **PASSENGER** Name Male Gender PASSENGER 3 **PASSENGER** Name Male Gender PASSENGER 4 **PASSENGER** Name Male Gender PASSENGER 5 PASSENGER Name Male Gender PASSENGER 6 PASSENGER Name Male Gender PASSENGER 7 PASSENGER Name Male Gender PASSENGER 8 PASSENGER Name

Page 2 of 15

Gender

Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

REFER WITH ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes No No

DETAILS OF OTHER VEHICLE PROPERTY 1

GBK5077P

Commercial vehicle

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category

Name of Driver Contact Number

Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

Accident report SK0L223S000L

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Orines
- information provided must be as invitried and accurate as possible. Any will ensure presentation or withholding of muterial
- facts may allow insurance companies to remodete policy liability. 4. The lasse and acceptance of this Form by inturance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore [GIA] for architeg and that copies of this report will for a fee be made available upon application by
- By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforeuld
- 8. Consent under the Personal Data Protection Act (PDPA)

funderstand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permissed to collect, with elisdose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or pussessed by my listurer (collectively the "Personal information") and disclose and transfer such in to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured rehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers Lawyers flaw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
 - (ii) investigating the accident and/or my claims;
 - [iii] carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (codectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Perconal information may/can be disclosed by any of the Incurers and/or GIA to their third party tentice prevides or agents including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time

Direr's Signature

fil diver a net the policyhe Date & Time

Acporting Centre Personnel's Signeture

NAIC/TIN No



A- PCIIE5X B= GBK5077P

femula road

	CRCUMST		-	ACCIDENT
PERCEIPE	CROUMST	INCES	UP THE	ACCIDENT

n 18/03/2012 @ 05-20 ha, my has pailles x mas chancing along punched had reglic high junction when a vehicle gersoner had my has par the parties from behind.	+
AR BOX III BOXING BOW PRING	
	_
	_
	-
	-
	_
	_
CLARATION	
te declare the foregoing particulars are true in every respect.	

Accident report SK0L223S000L

Page 5 of 15