

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/03/2022


User ID : GohKK2

Section A - Accident Details

Registration Number	SMB1631H
Case Reference Number	BUS/03/22/7010
Registration Date	13/2/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Lew Kok Fu
Type of Accident	Side Swipe
Accident Date and Time	14/3/2022 3:15 PM
Accident Reported Date and Time	14/3/2022 4:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1631H - REAR RIGHT PORTION SKR2052L (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	28/3/2022 10:09 AM
Chassis Number	WMAA22ZZ1F7002628
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,503.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 days
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	28/03/2022 10:14 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 28/03/2022

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	530
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	538
Total Spray Painting & Panel Beating	\$708.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009992	BODY RH	A01001-CW564	PANEL, SIDE: R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	R
6009990	BODY RH	A01001-CW565	PANEL, SIDE: R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	R
6009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE: R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	R
Total					\$2,685.90		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

R4m
 Hp 900 10068
 2 days
 4/5
 28/03/22 01420
 Res after repair