

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile								
	AXA INSURANCE	PTE LTD		Ref:	CS/ASM22002932/Kqy3			
	8 SHENTON WAY AXA TOWERSING	-		Date:	30/03/2022			
				Code:	ASM			
1.		Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SHA 1145J	Veh. Inspected	k	SJS 3195H			
	Policy No.		Coverage (\$)		0.00			
	Claim No.	S2M03X41	Excess (\$)		0.00			
	Assign From	CHAN Kian Chuan	Assign Date		30/03/2022			
2.	2. Vehicle Particulars & Condition							
	Make & Model		c.c		0			
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	-	Steering					
	Brakes		Modification					
	General							
3.		Condition	ons of Tyres					
		Size	Make		Balance			
	R/H Front Tyre				mm			
	L/H Front Tyre				mm			
	R/H Rear Tyre				mm			
	L/H Rear Tyre				mm			
4.		Description of Damages						
5.	General Information							
	Accident Date	29/03/2022	Inspection Dat	te	30/03/2022			
	Survey held at	RC AUTO						
		160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722						
5a.	. Remarks							
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							

AXA INSURANCE PTE LTD Ref: CS/ASM22002932/Kqy3

8 SHENTON WAY #24-01 Date: 30/03/2022 AXA TOWERSINGAPORE 068811

Code: ASM

. Policy Particulars :- THIRD PARTY CLAIM

Affiliated to Federation Internationale Des Experts En Automobile								
	Insured Veh.	SHA 1145J	Veh. Inspected	SJS 3195H				
	Policy No.		Coverage (\$)	0.00				
	Claim No.	S2M03X41	Excess (\$)	0.00				
	Assign From	CHAN Kian Chuan	Assign Date	30/03/2022				
2.	Vehicle Particulars & Condition							
	Make & Model		c.c	0				
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	-	Steering					
	Brakes		Modification					
	General							
3.	Conditions of Tyres							
		Size	Make	Balance				
	R/H Front Tyre			mm				
	L/H Front Tyre			mm				
	R/H Rear Tyre			mm				
	L/H Rear Tyre			mm				
4.		Description	on of Damages					
5.	_	General Information						
	Accident Date	29/03/2022	Inspection Date	30/03/2022				
	Survey held at	RC AUTO						
		160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722						
5a.	Remarks							
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							