



Service Requests

Messages

Claims



Service Request Details

Claim	S2M03X41
Reference	CS/ASM22002932/Kqy3e2 
Loss Date	28 March 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	30 Mar 2022 9:10:06 AM
Request Date	20 May 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SJS3195H
Vehicle	
Registration #	
Make	TPVD
Model	HYUNDAI

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages3InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2202990.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2022
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2022
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 May 2022
 AXA Immediate Advice - SJS3195H (TP).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	11 May 2022
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	30 March 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRS TP.pdf.pdf	Legal	Others	KUMAR Shailendra	30 March 2022
 PRI TP EMAIL FROM SOLICIOR.msg.msg	Legal	Others	KUMAR Shailendra	30 March 2022
 SHA1145J INS GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	30 March 2022
 SJS3195H TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	30 March 2022