

ASS. REC. BY:

REF:

CS/CT122002941/RV y3

5747

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV


To Inspect Vehicle No: SMK 3368Hat Workshop m/s CYCLE CARRIAGEof 209, PANDAN GARDENInsured: GBL 4667M CTIPolicy No. DMPCSNW00102052100Claims No. SNM22D202111/C02/TANKW

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 82K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMK3368H Yr Regn: 2019 / AARType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: KIA CERATO 1.6 A EX C.C. 1591Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 43759 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF3416MK5031166Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or _____Brake: In order / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 225/40R18R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/03/22 D.O.I. 18/04/22Survey held at CYCLE & CARRIAGE (P)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1/2 FRT & N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 53K

31/5/22

Rasul informed final fig \$7108 (Red 6983, 49%)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Days Of Repair: 6Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Date/Time, File Return to?

2) 31/5/22--typist

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Workshop (\$ _____)

S + RS. SI

Photos

Others

Report Format: Merimen



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG YONG JIE BLK 675D YISHUN AVENUE 4 #12-820 SINGAPORE 764675 Contact No Mobile: 91266270	Cust No/Name	/NG YONG JIE
	Reg No/Reg Date	SMK3368H*KC17/ 05/04/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031166
	Engine No	G4FGJH722094
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	18/04/2022/ 09:49	TLC	442 / CocoLu	48852			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1280 1600.00
RENEW FRT BUMPER, FRT FENDER RH								1100.00
E PNT98000								120.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH								60.00
B WHEELALIGNMENT120L								30.00
To Conduct Computerize Full Wheel Alignment								280.00
M SUNDRY								? 640.00
TRANSFER FRT RIM RH & LH								3000.00
A 90000001								260.00
CHECK WIRING & ELECTRICAL SYSTEM								40.00
A 10028901								? 950.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								30.00
A 90000001								100.00
RENEW FRT UNDER CARRIAGE								80.00
M SUNDRY								633.00
SUPPLY FRT RIM RH & LH								262.00
M SUNDRY								84.00
SUPPLY FRT TYRE LH 70% cut								14.00
M SUNDRY								164.00
SUPPLY FRT BUMPER SKIRT								
M SUNDRY								
REDO FRT BUMPER , FRT FENDER RH WRAPPING (insure)								
M SUNDRY								
Sundry								
E PNT88000								
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								
TOP UP AIRCON GAS								
M COVER-FR BUMPER ? photo?					1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER X					1.00	262.00	00.00	262.00
M ABSORBER-FRONT BUMPER ENERGY X					1.00	84.00	00.00	84.00
M AIR DUCT-FR BUMPER,RH ?					1.00	14.00	00.00	14.00
M LAMP ASSY-SIDE REPEATER,RH X					1.00	164.00	00.00	164.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing



CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NG YONG JIE	Cust No/Name /NG YONG JIE
BLK 675D YISHUN AVENUE 4	Reg No/Reg Date SMK3368H*KC17/ 05/04/201
#12-820	Date In/Mileage / 0
SINGAPORE 764675	Chassis No KNAF3416MK5031166
Contact No Mobile: 91266270	Engine No G4FGJH722094
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	18/04/2022/ 09:49	TLC	442 / Cocolu	48852

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M MOULDING-FRONT BUMPER,RH ?	1.00	36.00	00.00	36.00
M BRACKET-FR BUMPER UPR SIDE MTG ?	1.00	31.00	00.00	31.00
M PANEL-FENDER,RH 45	1.00	430.00	00.00	430.00
M LAMP ASSY-HEAD,RH ?	1.00	1247.00	00.00	1247.00
M GUARD ASSY-FRONT WHEEL,RH ?	1.00	95.00	00.00	95.00
M HUB ASSY-FR WHEEL ?	2.00	436.00	00.00	872.00
M ARM COMPLETE-FR LWR,RH ?	1.00	286.00	00.00	286.00
M ARM COMPLETE-FR LWR,LH ?	1.00	286.00	00.00	286.00
M BEAM COMPLETE-FR BUMPER X	1.00	686.00	00.00	686.00
M CARRIER ASSY-FRONT END MODULE ?	1.00	675.00	00.00	675.00

Estimate

SURVEYOR NAME: Pasme

SURVEYOR SIGNATURE: [Signature]

DATE: 18/04/22 @ 11:45

REMARKS: 6 days

Reey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

7% GST on **Nett** 14,091.00
986.37

Total Payable 15,077.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.

1. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/03/2022 16:15 (SGT)
Date of Accident	26/03/2022 13:20 (SGT)
Exact Location of Accident	Lentor Ave, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK3368H
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	NG YONG JIE
NRIC No	S8903574J
Email Address	jake.ngyongjie@gmail.com
Mobile Phone No	(Phone) +65-91266270
Alternative Phone No	+65-91266270

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900083019-01
Cover Note Number	-

DRIVER

Name of Driver	NG YONG JIE
NRIC No	S8903574J



Date Of Birth 26/01/1989
 Occupation Indoor
 Date Of Driving Pass 10/06/2011
 Driving experience 10 YEARS AND 9 MONTHS
 Gender Male
 Mobile Number (Phone) +65-91266270
 Alt. Phone Number +65-91266270
 Email Address jake.ngyongjie@gmail.com
 Address Blk 675D Yishun Avenue 4 #12-820
 Address complement -
 Postcode 764675
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Change/cross lane
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name Grace Lim Zhi Hui
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBL4667M
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle

er
mber

complement

de

ance Company Name

ure Of Damage

etails of property damaged in accident

no. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Angie Soh
Accident

X refers to impact point



Describe Circumstances of the Accident

Travelling along Lentor Avenue from Yishun to SLE.

Accident occurred somewhere in the middle of the distance from the junction of Yishun Ave 1 → SLE.

There was a road works in the center lane of the Lentor Ave and only Lane 1 and 3 was available

At the sight of roadworks, I drive in the lane 3, along the kerb and reservoir side, going straight.

One of the vehicle, GBL4667M, made the decision to filter out of the blocked lane and the accident happened.

His back wheels area and my right front bumper made contact and I was forced into the kerb, also damaging my left front wheels and rims.

We stopped along the road to exchange particulars

Policy Holder car: SMK3368H Kia Cerato

Other guy's car: GBL4667M Nissan NV200

Date: 26 Mar 2022

Time: 1:20 PM

Declaration

We declare the foregoing particulars are true in every respect.

 28/3/22
12PM
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
Angie Soh

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	574J
Vehicle No.:	SMK3368H
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Apr 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4FGJH722094
Chassis No.:	KNAF3416MK5031166
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$13,722.00
Original Registration Date:	05 Apr 2019
First Registration Date:	05 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$13,722.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Apr 2029
PARF Rebate Amount:	\$10,291.00
COE Expiry Date:	04 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,301.00
COE Rebate Amount:	\$18,305.00
Total Rebate Amount:	\$28,596.00

The information contained herein is correct as at 19 Apr 2022

OK

Kia Cerato 1.6A EX

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**CAR CHOICE**
SINGAPOREEUROPEAN
INDEPENDENT
ADVISORYSME500
SINGAPORE
2017 - 2018

CaseTrust

The Best Buying Experience

Price**\$79,800****Depreciation**

\$10,780 /yr

[View models with similar depre.](#)**Reg Date**

21-Jan-2019

(6yrs 9mths 1day COE left)

Mileage

43,000 km (13.3k /yr)

Manufactured

2018

Road Tax

\$738 /yr

Transmission

Auto

Dereg Value\$27,298 as of today ([change](#))**OMV**

\$13,858

COE

\$25,000

ARF

\$13,858

Engine Cap

1,591 cc

Power

93.8 kW (125 bhp)

Curb Weight

1,287 kg

No. of Owners

1