



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                          |                                                                                                                                        |                                                                                                                     |                                                              |            |
|--------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:CYNTHIA |                                                                                                                                        |                                                                                                                     | Ref: CC4/ASM22002952/Dea3q2<br>Date: 04/10/2022<br>Code: ASM |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                          |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            | Insured Veh.                                                                                                                           | SGU 1619R                                                                                                           | Veh. Inspected                                               | GBB 7102J  |
|                                                                                            | Policy No.                                                                                                                             | GA578546                                                                                                            | Coverage (\$)                                                | 0.00       |
|                                                                                            | Claim No.                                                                                                                              | S2M03X40                                                                                                            | Excess (\$)                                                  | 0.00       |
|                                                                                            | Assign From                                                                                                                            |                                                                                                                     | Assign Date                                                  | 30/03/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                              |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            | Make & Model                                                                                                                           | TOYOTA DYNA                                                                                                         | c.c                                                          | 2982       |
|                                                                                            | Engine No.                                                                                                                             | HIDDEN                                                                                                              | Year of Reg.                                                 | 2009       |
|                                                                                            | Chassis No.                                                                                                                            | JTFAT35YX0K200956                                                                                                   | Colour                                                       | SILVER     |
|                                                                                            | Odometer                                                                                                                               | -                                                                                                                   | Steering                                                     | IN ORDER   |
|                                                                                            | Brakes                                                                                                                                 | IN ORDER                                                                                                            | Modification                                                 | NIL        |
|                                                                                            | General                                                                                                                                | GOOD                                                                                                                |                                                              |            |
| <b>3. Conditions of Tyres</b>                                                              |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            |                                                                                                                                        | Size                                                                                                                | Make                                                         | Balance    |
|                                                                                            | R/H Front Tyre                                                                                                                         | 195 R15                                                                                                             | MAXXIS                                                       | 3 mm       |
|                                                                                            | L/H Front Tyre                                                                                                                         | 195 R15                                                                                                             | MAXXIS                                                       | 3 mm       |
|                                                                                            | R/H Rear Tyre                                                                                                                          | 155 R12 (D)                                                                                                         | MAXXIS                                                       | 4/4 mm     |
|                                                                                            | L/H Rear Tyre                                                                                                                          | 155 R12 (D)                                                                                                         | MAXXIS                                                       | 4/5 mm     |
| <b>4. Description of Damages</b>                                                           |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            | THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT, O/S FRONT & O/S REAR PORTION.<br>DAMAGES SEE DETAILS.                                  |                                                                                                                     |                                                              |            |
| <b>5. General Information</b>                                                              |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            | Accident Date                                                                                                                          | 28/03/2022                                                                                                          | Inspection Date                                              | 31/03/2022 |
|                                                                                            | Survey held at                                                                                                                         | ALFRED AUTO SERVICES & SUPPLIES<br>BLK 5035 ANG MO KIO 3 #01-355 ANG MO KIO INDUSTRIAL PARK 2 .<br>SINGAPORE 569538 |                                                              |            |
| <b>5a. Remarks</b>                                                                         |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                                     |                                                              |            |
| <b>5b. Estimate Days of Repair</b>                                                         |                                                                                                                                        |                                                                                                                     |                                                              |            |
|                                                                                            | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                                                     | 12 Working Days                                              |            |