

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	GREAT AMERICAN INSURANCE COMPANY		Ref:	CS3/GAI22002954/Rty3e2	
	3 TEMASEK AVEN TOWER SINGAPORE 0391	UE #16-01 CENTENNIAL 90	Date	: 06/04/2022	
			Code	e: GAI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBD 8422T	Veh. Inspected	SKR 6784G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CLMOMVC000004146	Excess (\$)	0.00	
	Assign From	SHERY WONG	Assign Date	30/03/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH 1.8 AUTO	c.c	1794	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	JTDER12W303001743	Colour	WHITE	
	Odometer	317920 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
	L/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
	R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
	L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA			
5.	General Information				
	Accident Date	29/03/2022	Inspect Date / Time	31/03/2022 (11:20 AM)	
	Survey held at	GUAN SIANG TRADING ENTER	PRISE		
		5034 ANG MO KIO INDUSTRIAL PARK 2 #01-317-5 SINGAPORE 569537			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	Report Ref No. CS3/GAI22002954/Rtv3e2				

Report Ref No. CS3/GAI22002954/Rty3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser