

ASS. REC. BY:

REF: LPC/ CS/LPC22002955/Kqy3Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. 21/22/22/VP05/025599Sum Insured: _____ Excess: ?

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$43k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLB 5705PYr Regn: 04, 16Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ford Focusc.c. 1596Colour: M White

A/C: Insured / Std / NI / NA

Sp. Reading: 103175

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W1F04XXGCC4FK27696Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 26/3/22D.O.I. 30/3/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Rear & etc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/3Maybe part by part, still unable to locate 2nd parts

31/03/22 @ 10.01am revert to Gerald by email.

31/03/22 @ 2.45pm Gerald informed C/A by email.

31/03/22 @ 3.26pm Informed wksp C/A on LS basis & ex-\$0/- by email.

Date/Time, File Pass to?



: Prell. Report



: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fines: _____

Others: _____

TOTAL

Add Fee: ☐

: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech Invs (\$ _____)



: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 5895

Not Withheld
1. B1, 11 Sy 8
Recovery After Paint

No. : 32285

Your Reference : Z21VP05028957

Accident Date : 26-Mar-2022

Date : 30-Mar-2022

Our Ref : 021725 / CARIN

PAGE : 1

6 days

Ex 8?

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

ESTIMATED COST OF REPAIR FOR FORD FOCUS 4DR TREND 1.6 (2016) SLB5705P
=====

1 pc rear bumper	Dis/mg cm	1,100.00	c	✓
1 pc rear bumper side retainer LH	cm	55.00	c	✓
1 pc rear bumper lower	sn	320.00	c	X
6 pcs rear bumper clip	na	45.00	c	✓
1 pc taillamp LH	cm	400.00	c	✓
1 pc taillamp panel	K	360.00	c	X
1 pc rear fender LH	B1	850.00	c	✓
1 pc rear fender inner air grille LH		125.00	c	7
1 pc rear fender inner shield LH	Dis	350.00	c	✓
1 pc rear fender 1/4 glass moulding	na	185.00	c	✓
1 pc rear windscreen glass moulding	RSP	165.00	c	X
1 pc rear door LH	B1	1,050.00	c	✓
1 pc rear door weatherstrip LH		185.00	c	
1 pc rear sport rim (original) 16 LH	na	950.00	c	✓
1 pc rear lower arm (big) LH		450.00	c	7
1 pc rear lower control arm LH		120.00	c	7
1 pc rear knuckle arm LH		600.00	c	7
1 pc rear knuckle arm c/w bearing LH		495.00	c	7
1 pc rear shock absorber LH		480.00	c	7
		8,285.00		
		Add 15% :	1,242.75	
				9,527.75
1 pc rear fender stone protection sticker LH	na	120.00	sn	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(興)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
 160 Sin Ming Drive #02-18/19/20
 Sin Ming AutoCity
 Singapore 575722
 Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : Z21VP05028957
 Our Ref : 021725

Page : 2
 No. : 32285

- 1 pc rear fender 1/4 glass sealant
- 1 pc rear fender 1/4 glass damping seal
- 1 pc rear windscreen glass sealant
- 1 pc rear windscreen glass damping seal
- 1 pc rear tyre LH

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

To remove and refit rear windscreen glass and conduct water leak test

To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works

To remove door's fittings

To dismantle and check rear under-carriage. To replace affected portions.

To conduct front wheel alignment test.

To putty and respray on affected portions.

To focus taillamps. To check rear wiring and lighting operation.

ma 30.00 sn
ma 15.00 sn ✓
ma 40.00 sn —
ma 20.00 sn —
ma 180.00 sn X

800
 1,200.00

120.00 ✓

100
 180.00

80.00 *600*

180.00 ?

80.00 *600*

800.00 *600*

30.00 *200*

Total : S\$12,612.75
 =====

Singapore Dollars Twelve Thousand Six Hundred and Twelve and Cents Seventy Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/03/2022 17:44 (SGT)
Date of Accident	26/03/2022 11:13 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JALAN MALU MALU
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5705P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ANTHONY MAK PUI YARN
NRIC No	SXXXX601I
Email Address	MYANTHONYMAK@GMAIL.COM
Mobile Phone No	(Phone) +65-91860186
Alternative Phone No	+65-91860186

VEHICLE PARTICULARS

Manufacturer	Ford
Model	Focus
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1596

INSURANCE COMPANY

Name of Insurance Company	Lonpac Insurance Bhd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	Z21VP05028957
Cover Note Number	-

DRIVER

Name of Driver	ANTHONY MAK PUI YARN
NRIC No	SXXXX601I

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &

Time 28/3/22 @ 2:45p

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A: SLB 5705P

B: XE 6860J

Jalan Melu Melu

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

601I

Vehicle No.:

Vehicle to be Exported:

SLB5705P

Intended Deregistration Date:

No

Vehicle Make:

28 Mar 2022

Vehicle Model:

FORD

Primary Colour:

FOCUS 4DR TREND 1.6 TI-VCT A/T

Manufacturing Year:

White

Engine No.:

2015

Chassis No.:

FK27696

Maximum Power Output:

WF04XXGCC4FK27696

Open Market Value:

92.0 kW (123 bhp)

Original Registration Date:

\$14,221.00

First Registration Date:

13 Apr 2016

Transfer Count:

13 Apr 2016

Actual ARF Paid:

3

Intended PARF Rebate Details

\$14,221.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

12 Apr 2026

PARF Rebate Amount:

\$9,954.00

Intended COE Rebate Details

COE Expiry Date:

12 Apr 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$46,009.00

COE Rebate Amount:

\$18,594.00

Total Rebate Amount:

\$28,548.00

The information contained herein is correct as at 28 Mar 2022

OK



Ford : Focus : 05/14-2018 (Focus 2015) : except Focus ST, RS : 4 Door, 5 Door
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°53'	-0°53'	-2°08' 0°22'
3°55'	3°55'	3°14' 5°14'
0°14'	0°07'	-0°03' 0°09'
14°57'	14°58'	
14°05'	14°05'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°03'	-1°03'	-2°08' 0°22'
4°11'	4°11'	3°14' 5°14'
-0°21'	-0°14'	-0°03' 0°09'
14°52'	14°52'	
13°49'	13°49'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°10'	0°10'	
-0°17'	-0°17'	
0°05'	0°06'	
-0°07'	-0°07'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-2°50'	-2°53'	-2°36' -0°06'
-0°01'	-0°02'	-0°01' 0°23'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°48'	-1°48'	-2°36' -0°06'
0°09'	0°09'	-0°01' 0°23'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°02'	-1°05'	
0°08'	0°07'	0°11' 0°35'
-0°05'	-0°05'	-0°30' 0°30'