



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ONG LAY HOON Reg No/Reg Date SMH8634Y / 13/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000635 Engine No 3A92UHL9319 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	30/03/2022/ 17:44	BLE	261 / Edwin Caina	22067			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								5400.00
RENEW FR BUMPER , BODY KIT , BONNET , LHF FENDER , RHF FENDER & FR SUPPORT PNL					5	450	+ 80	2330
REPAIR LHF DOOR , RHF DOOR & FR A PILLAR LH/RH								
E PNT98000								4200.00
RESPRAY FR BUMPER , BODY KIT , BONNET , LHF FENDER , RHF FENDER , FR SUPPORT PNL , LHF DOOR , RHF DOOR , FR A PILLAR LH/RH & FR CHASSIS					10	350		3500
E PNT88000								100.00
RENEW AC COND & RADIATOR								80.00
A 25000001								900.00
TOP UP AC GAS								
A 54900099								1350.00
RENEW DASHBOARD ASSY								
REMOVE & REFIT INSTRUMENT PNL , CENTER CLUSTER & RADIO								
A 11900199								900.00
REMOVE & REFIT ENGINE & GEARBOX ASSY								
A 54900099								450.00
RENEW DRIVER AIRBAG , PASSENGER AIRBAG , SENSOR & AIRBAG CONTROL UNIT								
A 54900099								30.00
RENEW FR SAFETY BELT & BUCKLE LH / RH								
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								1000.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
E PNT88000								120.00
CONDUCT CHASSIS ALIGNMENT-CELETTE BENCH								
B WHEELALIGNMENT120L								50.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								120.00
SUPPLY FR NUMBER PLATE WITH CASING								
M SUNDRY								80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ONG LAY HOON Reg No/Reg Date SMH8634Y / 13/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000635 Engine No 3A92UHL9319 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	30/03/2022/ 17:44	BLE	261 / Edwin Caina	22067
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
SUPPLY BODY PNL SEALANT					20 - 30.00
M SUNDRY					
Sundries					
M FACE,FR BUMPER / BR		1.00	811.00	23.00	624.47
M COVER,FR BUMPER / BR		1.00	12.00	23.00	9.24
M COVER,HEADLAMP SUPT PANEL / BR		1.00	62.00	23.00	47.74
M GRILLE,FR UNDER / BR		1.00	165.00	23.00	127.05
M GARNISH,FR BUMPER,LH ? x nm		1.00	127.00	23.00	97.79
M GARNISH,FR BUMPER,RH ? x nm		1.00	127.00	23.00	97.79
M BRACKET,FR BUMPER,LH / BR		1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,RH / BR		1.00	13.00	23.00	10.01
M CLIP,FR BUMPER / nec		5.00	4.00	23.00	15.40
M MARK,THREE-DIA / nec		1.00	70.00	23.00	53.90
M GRILLE,RADIATOR / BR		1.00	557.00	23.00	428.89
M HOOD / DD		1.00	737.00	23.00	567.49
M HINGE,HOOD,LH / BT		1.00	56.00	23.00	43.12
M HINGE,HOOD,RH / BT		1.00	56.00	23.00	43.12
M INSULATOR,HOOD / CRy		1.00	177.00	23.00	136.29
M CLIP,HOOD INSULATOR / nec		2 6.00	3.00	23.00	13.86
M LATCH,HOOD / BT		1.00	69.00	23.00	53.13
M FENDER,FR LH / DD		1.00	500.00	23.00	385.00
M FENDER,FR RH / DD		1.00	500.00	23.00	385.00
M SHIELD,FR WHEELHOUSE,LH ? x nm		1.00	98.00	23.00	75.46
M SHIELD,FR WHEELHOUSE,RH ? x nm		1.00	98.00	23.00	75.46
M CLIP,INNERSHIELD ? x nm		12.00	4.00	23.00	36.96
M PANEL ASSY,FR END / DD		1.00	1055.00	23.00	812.35
M PANEL,HEADLAMP SUPPORT,UPR / DD		1.00	66.00	23.00	50.82
M PANEL,AIR GUIDE,LH / BR		1.00	11.00	23.00	8.47
M PANEL,AIR GUIDE,RH / BR		1.00	11.00	23.00	8.47
M COVER,ENG ROOM UNDER,FR ? x nm		1.00	99.00	23.00	76.23
M HEADLAMP ASSY,LH / BR		1.00	663.00	23.00	510.51
M HEADLAMP ASSY,RH / BR		1.00	663.00	23.00	510.51
M LAMP ASSY,FOG,FR LH ? x nm		1.00	305.00	23.00	234.85

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ONG LAY HOON Reg No/Reg Date SMH8634Y / 13/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000635 Engine No 3A92UHL9319 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	30/03/2022/ 17:44	BLE	261 / Edwin Caina	22067
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY, FOG, FR RH	! x nn	1.00	305.00	23.00	234.85
M TANK, WINDSHIELD WASHER	CRU	1.00	75.00	23.00	57.75
M MOTOR, WINDSHIELD WASHER	x nn	1.00	30.00	23.00	23.10
M GASKET, W/SHLD WASHER MOTOR	? x nn	1.00	4.00	23.00	3.08
M HARNESS, CONTROL	? + nn	1.00	1245.00	23.00	958.65
M HARNESS, CHASSIS, FR	? + nn	1.00	1487.00	23.00	1144.99
M PANEL, AIR GUIDE	BR	1.00	112.00	23.00	86.24
M RADIATOR ASSY	DD	1.00	972.00	23.00	748.44
M TANK ASSY, RADIATOR COND	CRU	1.00	42.00	23.00	32.34
M FAN, COOLING	BR	1.00	77.00	23.00	59.29
M SHROUD, COOLING FAN	BR	1.00	131.00	23.00	100.87
M MOTOR, COOLING FAN	BR	1.00	484.00	23.00	372.68
M CONDENSER ASSY, A/C REFRIGE	DD	1.00	762.00	23.00	586.74
M SENSOR, AIR BAG, LH	NEC	1.00	293.00	23.00	225.61
M SENSOR, AIR BAG, LH	NEC x nn	1.00	293.00	23.00	225.61
M SPRING, AIR BAG SENSOR	NEC	1.00	319.00	23.00	245.63
M CONT UNIT, SRS DIAGNOSIS	NEC	1.00	609.00	23.00	468.93
M MODULE, AIR BAG	NEC	1.00	600.00	23.00	462.00
M MODULE, PASSENGER AIR BAG	BR	1.00	1672.00	23.00	1287.44
M PANEL, INSTRUMENT	CRU	1.00	730.00	23.00	562.10
M S/BELT, FR PRE-TENSIO, OTR L	Jammed	1.00	589.00	23.00	453.53
M S/BELT, FR PRE-TENSIO, OTR R	Jammed	1.00	589.00	23.00	453.53
M GARNISH, FR DECK	x nn	1.00	178.00	23.00	137.06
M COVER, FR DECK, LH	x nn	1.00	16.00	23.00	12.32
M COVER, FR DECK, RH	x nn	1.00	16.00	23.00	12.32
M GARNISH, FR PILLAR, LH	BR	1.00	30.00	23.00	23.10
M GARNISH, FR PILLAR, RH	BR	1.00	30.00	23.00	23.10
M SEAT BELT, FR SEAT, INR LH	? x nn	1.00	93.00	23.00	71.61
M SEAT BELT, FR SEAT, INR RH	? x nn	1.00	102.00	23.00	78.54
M DUCT, A/CLNR INTAKE	BR	1.00	131.00	23.00	100.87
M BODY ASSY, AIR CLEANER	? x nn	1.00	153.00	23.00	117.81
M COVER, AIR CLEANER	? x nn	1.00	45.00	23.00	34.65
M INSULATOR, ENG MOUNTING	? x nn	1.00	205.00	23.00	157.85

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ONG LAY HOON Reg No/Reg Date SMH8634Y / 13/02/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000635 Engine No 3A92UHL9319 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	30/03/2022/ 17:44	BLE	261 / Edwin Caina	22067			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	ROD ASSY,ENG ROLL STOPPER				1.00	155.00	23.00	119.35
M	INSULATOR,T/M MOUNTING				1.00	209.00	23.00	160.93
M	EMBLEM ECO				2.00	17.00	00.00	34.00
M	UNPAINTED BODYKITS				1.00	1643.00	20.00	1314.40
M	LLC 4L				1.00	26.00	23.00	20.02

Estimate

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

7% GST on **31690.72** **31,690.72**
Total Payable **2218.35** **33,909.07**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/03/2022 14:30 (SGT)
Date of Accident	29/03/2022 17:55 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	ALONG BKE, AFTER CAMERA ZONE, BEFORE EXIT TO KJE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH8634Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG LAY HOON
NRIC No	SXXXX507B
Email Address	shany_ong3@yahoo.co.uk
Mobile Phone No	(Phone) +65-90275063
Alternative Phone No	+65-90275063

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1193

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	190006484-02
Cover Note Number	-

DRIVER

Date of Birth	06/04/1993
Occupation	Outdoor
Date Of Driving Pass	06/10/2020
Driving experience	1 YEAR AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92209331
Alt. Phone Number	-
Email Address	wenbinQ93@gmail.com
Address	BLK. 180 BUKIT BATOK WEST AVENUE 8
Address complement	#07-171 SINGAPORE
Postcode	650180
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX1116A
Vehicle Manufacturer	Mercedes
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	SIVAGNANAM INDRANI
Contact Number	(Phone) +65-90678531
Address	

Code -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was travelling along BKE and it was ~~has~~ drizzling and floor was wet. ~~I was~~
It was heavy traffic and I was driving behind the Mercedes. The driver suddenly
jpm brake and I immediately jpm brake. However, even though I jpm brake
but still hit the vehicle. ~~I believe at that traffic~~


Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



Name of Policyholder	JOHN J. HONAN
Period of Insurance	12 Months from 1/1/50 to 12/31/50
Insurance Fee	\$10.00
Commission	\$2.00
Tax	\$0.50

Wichita Falls
Ft. Worth
Lubbock

ST Jan 2022

Model Number	MTS-1000A APPROX 12 CUB	Model Name	
Engine Capacity/Type	1.0 LITER	Engine Type	
Engine Modification	NA	Oil Marking	
Herat or Consignee of Purchase, Country of Origin			

First Year of Registration	2019
Business with COUPANE	Yes

[Faint, illegible handwritten notes at the bottom of the page]

1. 1970-1972 - 21 Aug 1972

2. 1973-1974 - 21 Aug 1974

3. 1975-1976 - 21 Aug 1976

4. 1977-1978 - 21 Aug 1978

5. 1979-1980 - 21 Aug 1980

6. 1981-1982 - 21 Aug 1982

7. 1983-1984 - 21 Aug 1984

8. 1985-1986 - 21 Aug 1986

9. 1987-1988 - 21 Aug 1988

10. 1989-1990 - 21 Aug 1990

11. 1991-1992 - 21 Aug 1992

12. 1993-1994 - 21 Aug 1994

13. 1995-1996 - 21 Aug 1996

14. 1997-1998 - 21 Aug 1998

15. 1999-2000 - 21 Aug 2000

16. 2001-2002 - 21 Aug 2002

17. 2003-2004 - 21 Aug 2004

18. 2005-2006 - 21 Aug 2006

19. 2007-2008 - 21 Aug 2008

20. 2009-2010 - 21 Aug 2010

21. 2011-2012 - 21 Aug 2012

22. 2013-2014 - 21 Aug 2014

23. 2015-2016 - 21 Aug 2016

24. 2017-2018 - 21 Aug 2018

25. 2019-2020 - 21 Aug 2020

26. 2021-2022 - 21 Aug 2022

27. 2023-2024 - 21 Aug 2024

28. 2025-2026 - 21 Aug 2026

29. 2027-2028 - 21 Aug 2028

30. 2029-2030 - 21 Aug 2030

31. 2031-2032 - 21 Aug 2032

32. 2033-2034 - 21 Aug 2034

33. 2035-2036 - 21 Aug 2036

34. 2037-2038 - 21 Aug 2038

35. 2039-2040 - 21 Aug 2040

36. 2041-2042 - 21 Aug 2042

37. 2043-2044 - 21 Aug 2044

38. 2045-2046 - 21 Aug 2046

39. 2047-2048 - 21 Aug 2048

40. 2049-2050 - 21 Aug 2050

41. 2051-2052 - 21 Aug 2052

42. 2053-2054 - 21 Aug 2054

43. 2055-2056 - 21 Aug 2056

44. 2057-2058 - 21 Aug 2058

45. 2059-2060 - 21 Aug 2060

46. 2061-2062 - 21 Aug 2062

47. 2063-2064 - 21 Aug 2064

48. 2065-2066 - 21 Aug 2066

49. 2067-2068 - 21 Aug 2068

50. 2069-2070 - 21 Aug 2070

51. 2071-2072 - 21 Aug 2072

52. 2073-2074 - 21 Aug 2074

53. 2075-2076 - 21 Aug 2076

54. 2077-2078 - 21 Aug 2078

55. 2079-2080 - 21 Aug 2080

56. 2081-2082 - 21 Aug 2082

57. 2083-2084 - 21 Aug 2084

58. 2085-2086 - 21 Aug 2086

59. 2087-2088 - 21 Aug 2088

60. 2089-2090 - 21 Aug 2090

61. 2091-2092 - 21 Aug 2092

62. 2093-2094 - 21 Aug 2094

63. 2095-2096 - 21 Aug 2096

64. 2097-2098 - 21 Aug 2098

65. 2099-2100 - 21 Aug 2100

66. 2101-2102 - 21 Aug 2102

67. 2103-2104 - 21 Aug 2104

68. 2105-2106 - 21 Aug 2106

69. 2107-2108 - 21 Aug 2108

70. 2109-2110 - 21 Aug 2110

71. 2111-2112 - 21 Aug 2112

72. 2113-2114 - 21 Aug 2114

73. 2115-2116 - 21 Aug 2116

74. 2117-2118 - 21 Aug 2118

75. 2119-2120 - 21 Aug 2120

76. 2121-2122 - 21 Aug 2122

77. 2123-2124 - 21 Aug 2124

78. 2125-2126 - 21 Aug 2126

79. 2127-2128 - 21 Aug 2128

80. 2129-2130 - 21 Aug 2130

81. 2131-2132 - 21 Aug 2132

82. 2133-2134 - 21 Aug 2134

83. 2135-2136 - 21 Aug 2136

84. 2137-2138 - 21 Aug 2138

85. 2139-2140 - 21 Aug 2140

86. 2141-2142 - 21 Aug 2142

87. 2143-2144 - 21 Aug 2144

88. 2145-2146 - 21 Aug 2146

89. 2147-2148 - 21 Aug 2148

90. 2149-2150 - 21 Aug 2150

91. 2151-2152 - 21 Aug 2152

92. 2153-2154 - 21 Aug 2154

93. 2155-2156 - 21 Aug 2156

94. 2157-2158 - 21 Aug 2158

95. 2159-2160 - 21 Aug 2160

96. 2161-2162 - 21 Aug 2162

97. 2163-2164 - 21 Aug 2164

98. 2165-2166 - 21 Aug 2166

99. 2167-2168 - 21 Aug 2168

100. 2169-2170 - 21 Aug 2170

101. 2171-2172 - 21 Aug 2172

102. 2173-2174 - 21 Aug 2174

103. 2175-2176 - 21 Aug 2176

104. 2177-2178 - 21 Aug 2178

105. 2179-2180 - 21 Aug 2180

106. 2181-2182 - 21 Aug 2182

107. 2183-2184 - 21 Aug 2184

108. 2185-2186 - 21 Aug 2186

109. 2187-2188 - 21 Aug 2188

110. 2189-2190 - 21 Aug 2190

111. 2191-2192 - 21 Aug 2192

112. 2193-2194 - 21 Aug 2194

113. 2195-2196 - 21 Aug 2196

114. 2197-2198 - 21 Aug 2198

115. 2199-2200 - 21 Aug 2200

116. 2201-2202 - 21 Aug 2202

117. 2203-2204 - 21 Aug 2204

118. 2205-2206 - 21 Aug 2206

119. 2207-2208 - 21 Aug 2208

120. 2209-2210 - 21 Aug 2210

121. 2211-2212 - 21 Aug 2212

122. 2213-2214 - 21 Aug 2214

123. 2215-2216 - 21 Aug 2216

124. 2217-2218 -

1. I hereby certify that the above is a true and correct copy of the original as shown to me by the person who submitted it to me.

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

Am. St. Chart. Assoc. 1970 Year 12 Proceedings 1974

11/11/2022 12:00:00 PM

© 2004 Blackwell Publishing Ltd *Journal of Internal Medicine* 255: 105–112

United States and Europe have shown

Mycoplasma mycoides - Borden, *Journal of Bacteriology*, 1908, p. 100.

APPROVED REPAIRING CENTRES AUTHORIZED REPAIRERS & COMPLAINTS RELATED REPAIRS

1. **Online Services:** **Asia Pacific** Inc. Asia Pacific Online Services Singapore 652251 68048877
2. **Online & Telephone Customer Service:** **Central** for customer handling & assistance (over-the-top) Asia Pacific Inc. Singapore 652251 67481820
3. **Online & Telephone Customer Service:** **Central** for customer handling & assistance (over-the-top) Asia Pacific Inc. Singapore 652251 67481820
4. **Online & Telephone Customer Service:** **Central** for customer handling & assistance (over-the-top) Asia Pacific Inc. Singapore 652251 67481820

1785-1786

Miss Purvisha Curran, Employer's Lien, May Bank

Source: <http://www.fda.gov/oc/ohrt/ohrt.html>

AIG Asia Pacific Insurance Pte. Ltd.

This document generated document does not contain any information