Meng Yan (LKK Auto)

From: Sent: To: Subject: Attachments:	Susan Low Susan Low Su
Categories:	Germaine
Accident on 29/03/2022 Along CTE Involving GBJ8325J and SMP2738D	
We refer to the above accident and 3rd party claims. We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.	
the damage to our client's veh	joint expert motor surveyors list (SJE) to conduct a pre-repair survey of nicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Kaki Bukit Singapore 417883 as soon as possible.
Kindly arrange.	
Thank you. Best Regard! Susan Low M/s Liu's Brother Auto Engineering Workshop No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6741 1730 Fax: 6744 5746	
Date of Survey:-	
Name of Authorise Surveyor:-	
Surveyor Email:	
Remark :	