

ASS. REC. BY:

REF:

88/LPC22003039/Tv43.

## ASSIGNMENT

LoE 2022 Aug

Yr Regn: 2012 / Aug

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 100

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$6000

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No:

XD5929H

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Tipper - truck

Make:

Isuzu CYZ52Lc.c. 15681

Colour

Gold

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JALCYZ52LC7000015Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/80R22.5

R:

~ ~ (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Golden Crown

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

11/4/22 25pm

Survey held at

Woon May Sg Kabin.Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / ☒ Body Structure affected due to collision.

Date / Time Action / Instruction

Total loss, Not Economical to repair.

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.I. (%)



# Woon Meng Motor Pte Ltd

50, Bukit Batok Street 23, #01-06  
Midview Building, Singapore (659578)  
Tel: 63161131/ 63161151 Fax: 63167050

Date : 30.03.2022

Particular of vehicle as follows :

Registration no : XD5929H  
Make/ Model : ISUZU CYZ52L  
Chassis no : JALCYZ52LC7000015

This vehicle has sustained serious damaged and is beyond economical repairs.

Please arrange for a surveyors to survey this vehicle.

Your faithfully

Woon Meng Motor Pte Ltd  
Tel : 63161131  
Fax : 63167050

**Auto Consumer's Guide**  
the Repairer of the follow:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97495749  
11/4/22 2:50 pm

OD Ex: to be advise  
Not Authorised.

taufik@lkhauto.com