

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/03/2022 12:35 (SGT) Date of Accident 28/03/2022 14:40 (SGT) **Exact Location of Accident** Bukit Timah Rd, Singapore Additional Location Information **BUKIT TIMAH TOWARDS SUNGEI ROAD** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Tovota

Vehicle Registration Number **GBF1228Z**

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner **SWC CONSTRUCTION** Company Reg No 5XXXX381D **Email Address** STANLEY@SWCCONSTRUCTION.COM.SG Mobile Phone No (Phone) +65-98394332 Alternative Phone No +65-98394332

VEHICLE PARTICULARS

Manufacturer

Model Dyna Variant 150 MANUAL Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Commercial vehicle Transmission Manual CC 2982

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage Comprehensive Fleet Policy No Policy Number DMCVSNW00154852104 Cover Note Number

DRIVER

Name of Driver SHAUN NG DING HAN NRIC No SXXXX322I

Date Of Birth 28/12/1992 Occupation Outdoor Date Of Driving Pass 19/09/2013 Driving experience 8 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-91871177 Alt. Phone Number **Email Address** SHAUNNDH@GMAIL.COM Address BLK 115 BUKIT BATOK WEST AVE 6 #13-204 Address complement

Postcode 650115
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Employee
Does Driver Own Other Vehicles? No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

PASSENGER 1

Name PASSANGER Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 28/3/2022, AT ABOUT 1440HRS. I WAS DRIVING ALONG BUKIT TIMAH ROAD TOWARDS SUNGEI ROAD. I WAS ABOUT 5 METRE FROM CROSS LINE. THE TRAFFIC LIGHT WAS GREEN LIGHT. VEHICLE B SUDDENLY STOPPED, I ACCIDENTLY BANG ONTO VEHICLE B BACK.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No
Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration NumberSMN3985KVehicle Manufacturer-Vehicle Model-Vehicle Variant-

Vehicle Colour
Vehicle Category
Name of Driver
NRIC No
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

Private hire
ROBIN CHUA SIOK SENG
SXXXX924H
(Phone) +65-90300784
-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

SWC CONSTRUCTION 7 GAMBAS CRESCENT

0 4 - 12 Policyholder 7 5g/13182

Date & ARK@GAMBAS

29/3/22

Driver's Signature

(If driver is not the policyholder)

Date & Time:

ie: 29/3/2)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIARMC SketchPlanForm_V3

SKETCH PLAN

ON 28/3/2022, AT	ABOUT 1440 HRS , I	L WAS DRIVING AL	ONG BUKIT TIMAH RO	AD TOWARDS SUI	UGEI ROAD.
I was about 5 I accidently bang	mehe from cress onto vehicle B Back	line. The transic ligi	let was green light.	Vehicle B subs	enly stopped
				-	

I/We declare the foregoing particulars are true in every respect.

SWC CONSTRUCTION
7 GAMBAS CRESCENT

#04-12
Policyholder's Sign 67087
Date & TimeARK @GAMBAS

Driver's Signature

(If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:

GIARMIC SketchPlanForm_V3



中国太平保险(新加坡)有限公司 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD.

Motor Commercial

MZ300/C

R SN AN0509A

Cov. Type:C

CERTIFICATE OF INSURANCE

CERTIFICATE No.

DMCVSNV00154852104

Engine No.: 1KD2622204 Cha. No.:JTFAT35Y10K206547

1 Index Mark and Regulation Number of Vehicle

GBF1228Z

AUTOSAFE

2. Name of Policy Helder

SWC CONSTRUCTION

30/12/2021 (00:00:00)

Excess Sect 1. EX ON WINDSCREEN . \$\$500.00 \$\$100.00

4 Date of Expry of Insurance

29/12/2022

Persons or Classes of Persons entited to drive?
 Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enscriment or regulation in that behalf from driving the Motor Vehicles

Use in connection with the Policyholder's business.
 Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
 Use for social, domestic or pleasure purposes.

The Poticy does not cover (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing. (2) Use whitst drawing a traiter except the towing of any one disabled mechanically propelled vehicle.

HIRE PURCHASE CO. GF MOTOR TRADING ENTERPRISE AS HP OWNER

* Limitations rendered inapprasive by Section 8 of the Motor Vehicles (Timel-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act. 1987 (Malaysia).

Please see reverse

Fe CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: NITA PTE LTD
Authorised Officer

China Taiping Insurance (Singapore) Pte. Ltd. (Co. Reg. No. 200208384E)

🛪 3 Anson Road #16-00 Springleaf Tower Singapore 079909

© 6389 6111

Auto Insure Pte. Ltd 6 Marsiling Lane 739145

Insurer Reference: GBF1228Z

Repairer Reference: M4626 / GBF1228Z Date calculated: 31/03/2022 12:54 PM



Full Report Registration: GBF1228Z Printed: 31/03/2022 12:54 PM

Summary Information

Claim

Location:

Printed by:

Singapore (SG)

GBF1228Z

5

Heng Cheng Chung

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

SGD

28/03/22

Currency: Date of Incident:

Hire Car Start:

Hire Car End:

Vehicle Details

Actual Repair Days:

Claim Reference:

Estimated Repair Time:

Vehicle

Manufacturer:

TOYOTA

Model:

DYNA

Sub Model: Model Sheet Number: BASE MODEL 70 1C 01

Registration:

GBF1228Z

VIN number:

JTFAT35Y10K206547

Odometer:

166422

Model Specs

AIR CONDITIONING STANDARD CAB

ASPHERICEL MIRROR TWO COAT METALLIC

4.0 LTR 73KW

WHEELBASE 2525MM

Steve (LKK) 1/4/22, 10.32

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

OD-M AL EXCEIS-?


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Tyres Condition

Tyre Brand Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right Outer),

Condition

mm

mm

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

Labour

	Time Base 10 WU/h	Price = 42.	00 SGD/h
Code	Description	WU	Price SGD
NO NUMBER	RENEW ENGINE COVER	60.0	252.00
NO NUMBER	R + R BADGE "DYNA"	2.0	8.40
520011	RENEW FRONT BUMPER INCLUDES: R + R BUMPER AND NECESSARY ATTACHED PARTS	10.0	42.00
751011	R + R RADIATOR GRILLE	3.0	12.60
810051)	R + R L/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.20
810051)	R + R R/HEADLAMP (RADIATOR GRILLE REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP	1.0	4.20
810151A	ADJUST HEADLAMPS	3.0	12.60
554011)	R + R WINDSCREEN INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS	30.0	126.00
670051)	R + R LEFT FRONT DOOR	3.0	12.60
670051)	R + R RIGHT FRONT DOOR	3.0	12.60

Code	Description		WU	Price SGD
743201)	DETACH + REFIT HEADLINING		4.0	16.80
883621)	R + R HEATING CPL		14.0	58.80
883611)	R + R EVAPORATOR		17.0	71.40
550451)	R + R INSTRUMENT PANEL		9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)		2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)		7.0	29.40
160011)	R + R RADIATOR		8.0	33.60
	INCLUDES: R + R FAN, FAN BLADE AND			
	EXPANSION TANK,			
	BLEED COOLING SYSTEM			
160011)	RENEW RADIATOR (RADIATOR REMOVED)		1.0	4.20
441101	R + R STEERING WHEEL		4.0	16.80
002889	DRAIN AND REFILL AIR CONDITIONING		7.0	29.40
1481	LEFT FRONT DOOR REPAIR		20.0*	84.00
1482	RIGHT FRONT DOOR REPAIR	100	20.0*	84.00
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	22.90	229.0	961.80
	Total of Labour			961.80

nt

Paint Work		Time Basis	10 WU/h
Code	Description - TWO COAT METALLIC	wu	Price SGD
LE 0413	ENGINE FIREWALL NEW PART PAINT ST 1	30.0	126.00
LE 0418	OUTER ENG FIREWALL NEW PART PAINT ST 1	8.0	33.60
LS 1481	LEFT FRONT DOOR REPAIR PAINT ST IV	25.0	105.00
LS 1482	RIGHT FRONT DOOR REPAIR PAINT ST IV	25.0	105.00
NO NUMBER	PREPARE FOR PAINTING	17.0	71.40

Spare Parts

				prices as at 201	5-06-01/01
Code		Description	Part Number	Part Source	Price SGD
0431		BADGE	75315 37080	Original TACK X NN	36.00
0433		BADGE MODEL	75311 37160	Original / ///	34.00 / 3
1002		BLACK GRANISH	FRONT	Original 4 / (V) nn	125.00
0413		ENGINE FIREWALL	55700 37440	Original / 00	480.00
0281		FRONT BUMPER	52111 37301	Original / 00	180.00
0410		GRILLE	53111 37891	Original / CK	190 175.00
1737		L/DOOR MIRROR ASSY	87940 37E63	Original / OR (Found mirror)	240.00
0887		L/END MOULDING	53814 37100A0	Original / OR	85.00
0293		L/F BUMPER BRACKET	52012 37033	Original / 00	0.00
1000		L/WIPER PANEL	FRONT	Original Y R	120.00
0571		LEFT HEADLAMP ASSY	81170 37121	Original / OR	265.00 /
0418	X	OUTER ENG FIREWALL	55078 37120	Original X //	0.00
0888	11	R/END MOULDING	53813 37100A0	Original / Re	115.00
0294		R/F BUMPER BRACKET	52011 37034	Original / OT	0.00

Description	Part Number	Part Source	Price SGD
R/WIPER PANEL	FRONT	Original / 00	120.00 /
RADIATOR	16400 78A80	Original X nn	0.00
RIGHT HEADLAMP ASSY	81130 37120		265.00
WINDSCREEN BOND KIT	PZ49I 00C1131	101	0.00
WINDSCREEN SEAL	56121 25040	× nn	0.00
Savings Subtotal			0.00 2,240.00
Total			2,240.00
	RADIATOR RIGHT HEADLAMP ASSY WINDSCREEN BOND KIT WINDSCREEN SEAL Savings Subtotal	R/WIPER PANEL FRONT RADIATOR 16400 78A80 RIGHT HEADLAMP ASSY 81130 37120 WINDSCREEN BOND KIT PZ49I 00C1131 WINDSCREEN SEAL 56121 25040 Savings Subtotal	R/WIPER PANEL FRONT Original 000 RADIATOR 16400 78A80 Original nn RIGHT HEADLAMP ASSY 81130 37120 WINDSCREEN BOND KIT PZ49I 00C1131 WINDSCREEN SEAL 56121 25040 nn Savings Subtotal

Extras

Code	Description	Price SGD
1003	CARPLATE AND HOLDER FRONT / ØT	25.00*
1004	AIRCON GAS FRONT / NOC	100.00*/
1005	COOLANT EPONT	50.00*
1006	SUNDRY FRONT Total Extras	20 50.00* 225.00

Final Calculation		471
AVMCQL SIRES ONLY	SGD	SGD
Parts	2,240.00	
Total Parts	THE STATE OF THE S	2,240.00
Labour Time Base 10 WU/h		
Total 229.0 WU X 42.00 SGD/h	961.80	852.60
Total of Labour		961.80
Total Of Extras		225.00
Paint Work Time Base 10 WU/h	441.00	407.40
Labour Cost 105.0 WU X 42.00 SGD/h Total Paint Including Material	441.00	441.00
		2 967 90
Repair Cost Excludes GST		3,867.80 270.75
GST (+7.00%) Repair Cost Included GST	To the second	4,138.55
Deductions (Excludes GST)		
Deduction For Excess	-500.00	
Total Of Deductions (Excludes GST)		-500.00
Grand Total Excludes GST		3,367.80
GST (+7.00%)		235.75
Grand Total Included GST		3,603.55