

Surveyor:

REF: CS1/LPM22003007/Rty3

Special Instruction:

ASSIGNMENT (Office)

From (Person): Bayusuria Zainal of LPM Date/Time: 31/03/2022

Estimated Cost: Bill to:

L/SUM : \$11,419.06 / 9 WORKING DAYS

Third Parties:

Claimant:

Surveyor: CA APPRAISERS PTE LTD

Workshop: AE AUTO PTE LTD

OD/TP Re-inspection **Evaluation**

To Inspect Vehicle No: SGR 9573B Insured: JRQ 8038

at Workshop m/s AE AUTO PTE LTD

Tel:

of BLK 19, SIN MING INDUSTRIAL ESTATE, #01-05 SINGAPORE 575677

Policy No: Claim No: 16/16/16/VP00/225405

Sum Insured: Excess:

Make of Veh: D.O.A. 13/11/2016
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 7 days)

Date/Time: 19/4/2022 Submit Final Fig 5400, 9 days (Red \$6019.06/ 52 %; Original 7 days)
LUMP SUM

Date/Time	Action/Instruction
	indicate note in report:
	market value: \$10,500(estimated)
	Ita: \$10,096.53(estimated)
	net value: \$403.47

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

- | | | | |
|--------------|--------------|--------------|----------------|
| 1) Date/Time | File Pass to | 2) Date/Time | File Return to |
| 3) Date/Time | File Pass to | 4) Date/Time | File Return to |
| 5) Date/Time | File Pass to | 6) Date/Time | File Return to |