



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MINISTRY OF DEFENCE AFPN 0042 321 GOMBAK DRIVE #02-05 SINGAPORE 669648			Ref: CC2/MIDA22003009/Tp Date: 30/06/2022 Code: MIDA	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SLK 1024A	
	Policy No. OA21021259	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From DHEVASEELAN	Assign Date	25/01/2022	
2. Vehicle Particulars & Condition				
	Make & Model FORD FOCUS	c.c	999	
	Engine No. HIDDEN	Year of Reg.	-	
	Chassis No. WF05XXGCC5GK13783	Colour	BLUE	
	Odometer 52206 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	6 mm
	L/H Front Tyre	205/55 R16	MICHELIN	6 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	6 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND ROOFTOP. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 26/04/2021	Inspection Date	04/04/2022	
	Survey held at BLK 288A BUKIT BATOK ST 25 (S) 650288 Repairer AUTOFRANCE			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	