

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



TP claim  
vehicle in.

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 61304

Page No. : 1 of 6

Date Estimated : 29/03/2022

Prepared By : Foong Shiuh Jye

**- ESTIMATE REPAIR FOR -**

Namgoong Sung  
15 Leedon Heights,  
#26-52

Singapore 266225

**- ACCOUNT - 238**

AXA Insurance Pte Ltd  
8 Shenton Way  
#24-01 AXA Tower  
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT4553K	WBATS720X09B88499	26/03/2020	X3 sDrive20i	21952

DESCRIPTION	VALUE
To replace bumper rear panel, boot lid, tail end panel, boot floor and knocking accident-affected area	6,800.00
To spray paint bumper rear panel, boot lid, tailend panel, boot floor. To repair accident affected area	3,940.00
To remove and install rear windscreen glass.	574.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	177.00
To replace front exhaust silencer including alignment system and conduct check for leak.	531.00
To replace rear exhaust silencer including alignment system and conduct check for leak.	531.00
To mount accident vehicle on celette bench or Car-O-liner to facilitate re-alignment of body / chassis accordance with BMW specification.	2,950.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.	531.00
To replace rear PDC sensor wire harness including reset and conduct check for proper function.	266.00
To carry out body cavity preservation. (Per panel).	118.00
To carry out body cavity preservation. (For cut panel).	531.00

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 61304**  
Date Estimated : **29/03/2022**  
Prepared By : **Foong Shiuh Jye**

Page No. : **2 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SMT4553K</b>	<b>WBATS720X09B88499</b>	<b>26/03/2020</b>	<b>X3 sDrive20i</b>	<b>21952</b>

DESCRIPTION	VALUE
To check electrical wiring system and lighting at the rear section for proper function.	177.00

Sundries.	150.00
-----------	--------

Total Labour 1: **17,276.00**

DESCRIPTION	QTY	PRIC	VALUE
RUBBER MOUNTING	1	33.70	33.70
SWING SUPPORT	1	45.95	45.95
TAILPIPE TRIM CHROME D=90MM	2	125.85	251.70
FRONT SILENCER	1	1,379.80	1,379.80
REAR SILENCER	1	1,353.40	1,353.40
EXCH CATALYTIC CONVERTER CLOSE TO E	1	2,096.50	2,096.50
RH TRUNK FLOOR	1	308.70	308.70
Luggage compartment floor,rear	1	729.25	729.25
INTERIOR TAIL TRIM PANEL	1	402.70	402.70
TRUNK LID	1	2,020.65	2,020.65
REAR BUMPER CARRIER	1	765.35	765.35
LH SIDE GUIDE FOR BUMPER	1	134.30	134.30
RH SIDE GUIDE FOR BUMPER	1	134.30	134.30
LH BUMPER GUIDE	1	161.15	161.15
RH BUMPER GUIDE	1	161.15	161.15
REAR BUMPER BOTTOM REINFORCEMENT	1	80.25	80.25
REAR BUMPER PANEL PRIMED (BASIS PMA	1	1,539.85	1,539.85
REAR BUMPER CLADDING (PDC)	1	611.15	611.15
REAR BUMPER TOWING EYE COVER	1	48.10	48.10
EMBLEM GROMMET	2	0.95	1.90
PLAQUE 82MM	1	72.85	72.85
LETTERING X3	1	65.60	65.60
LOCK TRUNK LID	1	230.30	230.30
TRUNK LID POWER LOCK PANEL	1	242.85	242.85
RH SPINDLE DRIVE	1	483.30	483.30
STRIKER BOOT LID	1	58.90	58.90
SPRING SUPPORT FOR VIBRATION ABSORB	1	315.65	315.65
Lashing rail, right	1	119.10	119.10
Storage compartment right	1	56.85	56.85
FLOOR CARPET LUGGAGE COMPARTMENT (S	1	634.25	634.25
REAR SILENCER centre (4800)	1	0.01	0.01
REAR SILENCER RH INSULATION	1	77.30	77.30
LOADING SILL COVER (EDELSTAHL)	1	221.95	221.95
REAR SILENCER HEAT INSULATION	1	77.30	77.30
RH GUTTER STRIP	1	39.60	39.60
LOWER TAIL LID TRIM PANEL (ELFENBEI	1	423.75	423.75
Control unit, smart opener	1	506.60	506.60
SENSOR WIRE FOR SMART OPENER TOP	1	46.55	46.55
SENSOR WIRE FOR SMART OPENER BOTTOM	1	51.20	51.20
RH REFLECTOR	1	39.05	39.05

**Performance Motors Limited**

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 61304  
 Date Estimated : 29/03/2022  
 Prepared By : Foong Shiuh Jye

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMT4553K	WBATS720X09B88499	26/03/2020	X3 sDrive20i	21952

DESCRIPTION	QTY	PRIC	VALUE
REAR LH LIGHT IN THE TRUNK LID	1	409.80	409.80
REAR RH LIGHT IN THE TRUNK LID	1	409.80	409.80
ULTRASONIC SENSOR BLACK	4	251.20	1,004.80
DECOUPING RING PDC TORQUE CONVERTER	4	5.15	20.60
CONTROL UNIT PARKING ASSISTANT	1	557.95	557.95
REVERSING CAMERA (ICAM2RFK BO01)	1	725.60	725.60
Total Parts :			<b>19,151.36</b>



Labour 1	:	17,276.00
Parts	:	19,151.36
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,549.92
Grand Total	:	<b>38,977.28</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	28/03/2022 19:46 (SGT)
Date of Accident	27/03/2022 10:45 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SMT4553K
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT4553K

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NAMGOONG SUNG
NRIC No	SXXXX384H
Email Address	SUNGNAMGOONG@GMAIL.COM
Mobile Phone No	(Phone) +65-92975000
Alternative Phone No	(Home) +65-65015625

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	X3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

### INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SD22V03550/MPC2/R01
Cover Note Number	-

### DRIVER

Name of Driver	NAMGOONG SUNG
NRIC No	SXXXX384H

Date Of Birth	28/02/1970
Occupation	Indoor
Date Of Driving Pass	05/04/2008
Driving experience	13 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-92975000
Alt. Phone Number	(Home) +65-65015625
Email Address	SUNGNAMGOONG@GMAIL.COM
Address	15 LEEDON HEIGHT
Address complement	#28-52
Postcode	266225
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	LEE SO YEOW
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFP9981D
Vehicle Manufacturer	BMW
Vehicle Model	530i
Vehicle Variant	-
Vehicle Colour	-

Vehicle Category	Private car
Name of Driver	LAI CHIONG LUNG DAVID
NRIC No	SXXXX412G
Contact Number	(Phone) +65-97578393
Address	-
Address complement	-
Postcode	-
Insurance Company Name	AXA Insurance Pte Ltd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person	-
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

### WITNESS DETAILS

#### WITNESS 1

Name	KEVIN W CHANG
Phone	(Phone) +65-90585740
Email	-

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

28/3/2022 8:16 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DRIVING down the Petir Road and to make left turn at T-Section (Petir Road and Dairy Farm Road), I made a stop to look right side of me as cars were coming (pls see above sketch) and all of sudden a very hard crash came from the back. The car from behind (SFP 99810) came at very high speed despite my car was ~~at~~ at stall not moving (to give the right way to the right ~~side~~ side of incoming cars which has the right way) in the first lane among two. The car behind was at high speed even his airbags deployed. This intersection especially when the incoming cars from the Dairy Farm Road you ~~had~~ must stop and look before proceed. I have been driving this road every Sunday as my church is nearby and therefore know the intersection very well. I don't think the car from behind (SFP 99810) was looking at my car and ~~pressed~~ brake not sure if he pressed brake because it is absolute not normal to speed as he did in that intersection whereas typical driving speed should be only 5-10 kmh coming into the curb and should stop and then proceed to enter into the Dairy Farm Road. This accident is 100% at fault from SFP 99810.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

28/03/2022 8:44 AM

© 2019/2020 NRIC Singapore, V3

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

## INSURER ENQUIRY

**Find  
insurer**

Vehicle reg. no.

SFP9981D

Date of Accident

27/03/2022 **Reset**% **RESULT & RECEIPT**

## TP Insurer Enquiry

Insurance ..... **AXA Insurance Pte Ltd**Period of Insurance ..... **13/04/2021 - 12/04/2022**Requested By ..... **Chan Sook Ling (Performance ...**Requested Date ..... **29/03/2022 14:45****Payment details**Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2****General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**