

ASS. BY: REF: CCG/ALG22003037 Dpa3

ASSIGNMENT

From: _____ Date: _____
Estimate Cost: _____
OD / RES / P RES / DD RES / EVA / INV / MV
To Insp Vehicle No: _____
at Work on m/s _____
by _____
Insurance _____
Policy # _____
Chassis # _____
Sum Insured: _____ Excess: _____
(Check record)
Make Owner: _____


Veh No: SJW 4477S Yr Reg: May 2017
Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Kia Cerato K3 OD 1591
Colour: Gray A/C: Insured / Not / NA
Sp. Reading: 263757 T/Radio: Insured / Not / NA
Eng/No: G4PGGH1641704
C/No: KNAFX41MH15720676
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: RE / ST / STD A/Rim or

Tyre Size: F: 205/55 R16
R: 11
SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUPA /
TOYO / YOKO or Yokohama

Front		Rear	
R/Bal	<u>S</u> mm	R/Bal	<u>S</u> mm
L/Bal	<u>S</u> mm	L/Bal	<u>S</u> mm
D.O.A	<u>30/03/222</u>	D.O.I	<u>01/04/2022</u>
Survey held at	<u>Alfred And AMK</u>		

Des. of Damages: Fit / Rear / O/S / H/S / W/C / Rooftop or
Rev

The W/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bel. of Market Value: _____
IDA/C Auxiliary Report _____ Consistent? : Yes or No
GIA / PR Seen _____ Consistent? : Yes or No
Est. Repairs: 54 days Res.: Yes or No
Lima Sum: 20 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date/Time	Action/Instruction
	ALG GBH 6587T
	MV 561C
	LTA 36.2K
	HL 19.8K
09/05/22	Insured 43 5,550/- with 5 days 2 rev