

REF:

## ASSIGNMENT

Veh No: 8LMS 2839. Yr Regn: 2017, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.C. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading 57177. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BN22A8A042168

Gen. Cond. Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: Inorden / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 50 R17.

R. 215/50 R17

N/S	O/S

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO OF

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 01/04/22

Survey held at NSK.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China.
	MV :
	PV :
	Nett :
	408D

☐ : Prel. Report  
☐ : Final Report

Resurvey No. of Trip:

Add Fee:  : Site Insp. (\$)

Site Insp (\$

□: Interview (3)

Journal of Interpersonal Violence 28(10)

Transportation:

$$S + RS \rightarrow S$$

Photos

1	Others	
---	--------	--