

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 31/03/2022
User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
REMOVE & REFIX FRONT RHS VIEW MIRROR	\$530.00	265
Total Labour	\$530.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	\$500.00	? m
Total Other Costs	\$500.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
013174			MIRROR, ELECTRIC OFF-SIDE, VOLVO B9TL, B5LH	1.00	\$412.78	0.00	\$412.78	Replace	cm
Total					\$412.78		\$412.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Agreement to Notify

the Repairer

- To resurvey and re-survey
- To display damage information
- Parts price on "at Prejudice" basis
- Third party involved
- No illegal work
- Supplier is resurveyed and approved by Insurance Company

Acknowledged by
Signature
Date

265.00
412.78
677.78

206
542.22

500.00

1042.22

45-1050

Pasue

Hy 20010068

1 day

4/5

31/03/22 After

Resy after repair

265

500

412.78