

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	Ro	ef:	CS3/ASM22003065/Tqy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Da	ate:	27/04/2022	
	ATTN: ANG YVON	NE	Co	ode:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 8096D	Veh. Inspected		GBG 5687A	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M03XEY	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		04/04/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JTFAT35Y00K208919	Colour		SILVER	
	Odometer	165184 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/75 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	195/75 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	155/55 R12 (D)	YOKOHAMA		6/6 mm	
	L/H Rear Tyre	155/55 R12 (D)	YOKOHAMA		6/6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
5.	General Information					
	Accident Date	31/03/2022	Inspect Date / Tin	me	06/04/2022 (12:22 PM)	
	Survey held at	V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/ASM22003065/Tqy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser