




## Service Request Details

Claim

S2M03X83

Reference

CS3/ASM22003068/Rqy3 

Loss Date

29 March 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

31 Mar 2022 10:30:46 AM

Request Date

4 April 2022

Due Date

4 April 2023

Services

Pre-Repair Survey

### Actions

---

Next Step

Finish the work

More ▼

## Vehicle Information

Incident Vehicle Registration #

GV9886C

Make

TPVD - Nissan

Model

P/UP FLATBED

## Service Address

, , ,

## Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

## Claim Handler

NG Stacey

stacey.ng@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes



Menu

TYPE



SENT

4/4/22 11:54 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

S2M03X83

BODY

Dear Stacey, Thank you for the assignment. Please ...

