



Your Ref: S1M03KYI

Date: 06th Apr 2022

Our Ref: CS3/ASM21011090/Tqy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Kitty Teo

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLQ 5025P
INSURED VEHICLE: SHA 2902J
ACCIDENT DATE: 26/10/2021**

We thank you for your instruction on 04/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLQ 5025P from M/s Pal's Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLQ 5025P and SHA 2902J.
- c) Final Repair Bill of SLQ 5025P from M/s Z-One Automotive Pte Ltd.
- d) Colour damaged vehicle photographs of SLQ 5025P.

Pre-Repair Inspection Date : 08/11/2021 at M/s 1 Kaki Bukit Avenue 6 #01-87 Autobay@Kaki Bukit, Repairer: Z-One Automotive Pte Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLQ 5025P
Make & Model	: Honda Step Wagon Spada 1.5 CVT ABS D/Airbag
Year of Registration	: 2017
Chassis Number	: RP31039593
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.