

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305511092
Date 07.04.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6543 8158

FINALIZATION FORM

To : LKK
Attn : Mr THEVAN
Vehicle Reg No. SHA32385

Fax :

Date of Accident : 31.03.22


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBT2176J
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$823.92
(b) Labour Charges	\$860.00
Total for Part-By-Part Repair Cost	\$1,483.92
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 82148315
Fax : 85468158

Signature : 
Name : THEVAN
Date : 25/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NMC (PIP)

Date: 01.04.2022

Time: 15:34:24

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305511092
 REGN NO : SHA3236S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 06.01.2021
 DATE/TIME IN : 01.04.2022 12:25
 ACCIDENT DATE : 31.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	DI
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	MC
0003 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	Sc
0004 04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	MC
0005 04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	Sc
0006 04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16	Sc
0007 09-01-0104-2184-G	UNIT ASSY-BSD LH	1	1,784.40	20.00	1,427.52	Sc

SUB-TOTAL : 2,567.28

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 L	REMOVE/REFIX REVERSE SENSOR	50.00	30

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305511092
 REGN NO : SHA3236S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 06.01.2021
 DATE/TIME IN : 01.04.2022 12:2
 ACCIDENT DATE : 31.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 800.00

TOTAL : 3,367.28

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Thuvan

82235769

1/4/22 1615

PIP repair 2dayswp

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.04.2022

Time: 09:50:44

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305511092
REGN NO : SHA3236S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 06.01.2021
DATE/TIME IN : 01.04.2022 12:25
ACCIDENT DATE : 31.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0003 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0004 04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64
0005 04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16

SUB-TOTAL : 823.92

JOB NATURE

0000 PB	PANEL BEATING (SHA3236S)	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 660.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.04.2022

REPAIR ESTIMATE

Time: 09:50:44

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305511092
REGN NO : SHA32368
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 06.01.2021
DATE/TIME IN : 01.04.2022 12:2
ACCIDENT DATE : 31.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,483.92

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :