

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI22003128/VQY3N2**Date:** 26/04/2022REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SHA896G**Insured Vehicle No :** SMQ1428A

Date of Loss: 03/04/2022

Nature of Claim: TP

Claim No: DM22HO00514

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA896G**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEJU166511

Reg. Date: 01/03/2019 (Man. Year: 2018)

Chassis No: KMHC851CVKU133735

Colour: Yellow

Odometer: 504984 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,342.04	563.52	778.52	58.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	1,230.00	290.00	19.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,862.04	1,793.52	1,068.52	37.33
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	2,862.04	1,450.00	1,412.04	49.34
+ GST 7.00/7.00% (S\$)	200.34	101.50	98.84	49.34
Nett Amount (S\$)	3,062.38	1,551.50	1,510.88	49.34

INSPECTION

Date of Assignment: 05/04/2022 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 06/04/2022 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2022)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA896G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CLIPS	Necessary	2.20 FL	*2.20 FL
3	1		*REAR BUMPER CENTER MOULDING	Serviceable	451.25 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Necessary	55.80 FL	*55.80 FL
5	1		*REAR WHEEL CAP LH	Scratched	346.40 FL	*346.40 FL
6	1		*REAR FENDER (PETROL ONLY) LH	Necessary	40.00 F	*40.00 FS
7	2		*REAR FENDER ADVERTISEMENTS STICKER RHLH	Necessary	200.00 F	*200.00 FS
8	1		*REAR BUMPER MAT	Serviceable	50.00 F	*- FS
					Sub Total (\$\$)	1,605.05 644.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	263.01 80.88
					Total Parts (\$\$)	1,342.04 563.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING - REAR FENDER ARCH LH	New	800.00	700.00
2	SPRAY PAINTING	New	600.00	500.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (S\$)			1,520.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >