

ASS. REC. BY: Thuvan

REF: CS3/CTI 22003140/0043

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: 16k

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**

GIA / PR Seen: _____ Consistent? : **Yes** or **No**

Est. Repairs: 5 days Res.: **Yes** or **No**

Lum Sum: _____ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: FBP 2830A Yr Regn: 9/3 119

Type: **M**.Car / **M**.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 292

Make: Yamaha Xmax 300 c.c. 299

Colour: black A/C: **Insured / Std / NI / NA**

Sp. Reading: not avail T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: MH35H08ulhk006195

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi: **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 110/70-14

R: 140/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 11/3/22 D.O.I. 5/4/22 1400

Survey held at Dnh Automotive

Des. of Damages: **Frt** / **Rear** / **O/S** / **N/S** / UIC / Rooftop or

The **UIC / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	mv: 16k
	rebate: 1999
	rw: 1400
	rr: 2.5k-3k

Date/Time, File Pass to?

: **Prel. Report**

: **Final Report**

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

_____ S + RS, _____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	294B
Vehicle Details	
Vehicle No.:	FBP2830A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Apr 2022
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	H336E0049269
Chassis No.:	MH35H0841KK006195
Maximum Power Output:	-
Open Market Value:	\$4,318.00
Original Registration Date:	09 Mar 2019
First Registration Date:	09 Mar 2019
Transfer Count:	1
Actual ARF Paid:	\$648.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,889.00
COE Rebate Amount:	\$1,999.00
Total Rebate Amount:	\$1,999.00

The information contained herein is correct as at 06 Apr 2022

OK

CP: 195

7 yrs 84

$$195 \times 84 = 16380$$
$$= 16k$$

16k - 1999

$$= 14001$$

4/6/22, 10:43 AM

Used Yamaha Xmax 300 bike for Sale in Singapore - Price, Reviews & Contact Seller - SGBikemart

Registration Date	27/05/2019
COE Expiry Date	26/05/2029 <small>Type: F1 (Nov 2018) 2009 (2019)</small>
Mileage	15000km
No. of owners	1
Type of Vehicle	Scooters

SGD \$16800

Registered May 2019 Yamaha Xmax 300.
 Super Low Total Milage Till Date.
 Accident Free.
 Only Use For Daily Work Commute.
 Read more 

[View More](#)

Similar Bikes



06/02/2022 Used Bike
 ★ Direct Seller
Yamaha Xmax 300
 Nov 2018 Model Yamaha Xmax 300

\$22000

♥ 2



09/02/2022 Used Bike
 ★ Direct Seller
Yamaha Xmax 300
 Selling My Pre-owned Yamaha X...

\$16900

♥ 0