

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



		AO I OMOBILE INOI			• -	
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC22003162/Vtcs2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE DI 189556				23-05-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLU 4108U	Veh. Ir	spected	SHD 4133H	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1167377-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	06/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	C.C		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVLU190489	Coloui	•	BLUE	
	Odometer	265256	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST		5 mm	
	L/H Front Tyre	195/65 R15	WEST		5 mm	
	R/H Rear Tyre	195/65 R15	WEST		5 mm	
	L/H Rear Tyre	195/65 R15	WEST	_AKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/04/2022	Inspec	tion Date	04/04/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	ia. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
_	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				