

Date/Time: 04.04.2022 15:56

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4192534

JC NO305511394

CUSTOMER

IR/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)
(P)

REGN NO: SHD4133H

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL: IONIQ(G3)

DATE/TIME IN 04.04.2022 13:20

YR OF MANU 19.12.2019

TARGET DATE

CHASSIS CODE KMHC851CVLU190489


COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 04.04.2022
NATURE: 3P 04.04.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHD4133H

YY

Vehicle No.:

SHD4133H

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORT TRANSPORTATION PTE LTD.

REPAIR ESTIMATE

Vehicle No. : SHD4133H

Make : HYUNDAI

Model : IONIQ(G3)

Date: 04.04.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
	RADIATOR GRILLE			\$ 1,409.10	Cell
	FRT NUMBER PLATE GARNISH			\$ 188.00	Cru
	UNIT ASSY SMART CRUISE RADAR SENSOR			\$ 2,910.90	7.
	FRT BUMPER			\$ 430.90	Cut
	FRT BUMPER REINFORCEMENT			\$ 1,075.10	7.
	FRT BUMPER REINFORCEMENT ABSORBER LH RH		\$ 93.25	\$ 186.50	7.
	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50	XV
	FRT BUMPER BRACKET TOP LH RH		\$ 35.00	\$ 70.00	hec
	FRT BUMPER SIDE BRACKET LH RH.			\$ 56.00	hsc
	FRT BUMPER CLIPS			\$ 22.00	mal
	FRT BUMPER CENTRE GRILLE			\$ 318.80	can SUC
	FRT BUMPER LOWER GRILLE MOULDING			\$ 127.60	X SUC
	HEADLAMP SUPPORT PANEL ASSY			\$ 949.30	X SUC
	SUB TOTAL			\$ 8,112.70	
	LESS 20%			\$ 1,622.54	
	DISCOUNTED TOTAL			\$ 6,490.16	
1	FRT NUMBER PLATE WITH TRIM COVER			\$ 55.00	mi 5
				\$ 55.00	nett
	Labour Charge			\$ 1,100.00	350
	PANEL BEATING			\$ 300.00	250
	SPRAY PAINTING CHARGE			\$ 1,400.00	
	TOTAL LABOUR			\$ 1,400.00	
	Emblem-Blue Drive (LH/RH)				
	ESTIMATE TOTAL			\$ 7,945.16	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan

92235769

4/4/22 1730

L/S repair

Zelays wp