

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	05 Apr 2022 10:59	05 Apr 2022 11:16 S\$ 19,410.42	05 Apr 2022 16:24 Edit Adj Rpt			Pending for Survey Report

CLAIM SUBFOLDER DETAILS

Insured:	CCPL , Co. Reg. No. : 199502839G		
Main Claimant:	CCPL		
Vehicle Reg. No.:	SHB4803T	Date of Loss :	01/04/2022 16:00 - :59 [55 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / DM22HO00510	Policy/Cover Note No. :	
Vehicle Reg. No. (Insured):	GBE5553M	Policy No. (Claimant):	
		Excess:	S\$3,000.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Jaime Tay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Thevan Thomas Karthikesavan] ... [Final Rpt due 14/04/2022]		
Adj Asg. Remarks:	SURVEY & REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/Assigned To	Note	Created On	Created By	1st Read By
No results.							

ADJUSTER'S CLAIM REFERENCE

Assignment From:	EQ Insurance Company Ltd (HQ)		
Adj File Ref No:	CS/EQI22003167/VTY3	Assignment Date:	05/04/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:	DM22HO00510	Recmd'd Resv. (S\$):	
Manager:	DENISE TAY KWEE CHENG	Adjuster:	Thevan Thomas Karthikesavan
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	ComfortDelGro Engineering Pte Ltd (Loyang) (from est.) (Check-in: 05/04/2022)		
Assignment Remarks:	SURVEY & REVERT		

DESCRIPTION OF VEHICLE

Vehicle Model:	TOYOTA PRIUS 1.5 HYBRID (A)					
Engine No:	2ZRS054792			Chassis No:	JTDKB3FU703560854	
LTA Reg Date (Man Yr):	17/08/2017 (2017)					
Colour of Vehicle:	Yellow			Odometer Reading:	389597 km	

CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	
Description of Accident/Loss:			

DOCUMENTS CHECKLIST

All Completed

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Assessment Reports

- ComfortDelGro Engineering Pte Ltd (Loyang) [Thumbnails]:(05/04/22) Repairer Estimates

Documentation

- ComfortDelGro Engineering Pte Ltd (Loyang) [Thumbnails]:(05/04/22) E-filed GIA report