

...CLAIM SUBFOLDER...(Pending for Survey Report)

THE REPAIRER HAS NOT SUBMITTED THEIR ESTIMATES

If you wish to work on the report, contact the repairer below to submit it.
You can authorize repairer submission after **5 days**.

0.1 days have passed since assignment.
You can authorize the submission of the repairer's estimates in **118 HOURS**.

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Apr 2022 08:44		06 Apr 2022 09:54				Pending for Survey Report Cancel Case

CLAIM SUBFOLDER DETAILS

Insured:	COMFORTDELGRO RENT-A-CAR PTE LTD , Co. Reg. No. : 775H		
Vehicle Reg. No.:	SFH8800S	Date of Loss :	25/03/2022 00:00 - :59 [52 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No. :	D20MFL0000326_01 (Comprehensive)
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837613		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Gabriel Wee - 63476100 ext 248]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/04/2022]		
Driver/Custodian:	CALVIN LOW BAO CAN () Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/Assigned To	Note	Created On	Created By	1st Read By
No results.							

ADJUSTER'S CLAIM REFERENCE

Assignment From:	India International Insurance Pte Ltd (HQ)		
Adj File Ref No:	CS/III22003168/KVY3	Assignment Date:	06/04/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:		Recmd'ed Resv. (S\$):	
Manager:	VERON CHEN	Adjuster:	KENNETH KONG
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	ComfortDelGro Engineering Pte Ltd (Braddell) (from est.) (Check-in: 06/04/2022)		

DESCRIPTION OF VEHICLE

Vehicle Model:	VOLVO V60 2.0 T2 CROSS COUNTRY (A)					
Engine No:	B4204T112215713			Chassis No:	YV1FZ40LDJ2045410	
LTA Reg Date (Man Yr):	16/11/2017 (2017)					
Colour of Vehicle:	White			Odometer Reading:	10000 km	

CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	

Third Party Involved?	Yes	TP Injury Involved?	No
Description of Accident/Loss:			

DOCUMENTS CHECKLIST

All CompletedResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Documentation

- India International Insurance Pte Ltd (HQ) [Thumbnails]:(06/04/22) Singapore Accident Statement