



Claim	S2M03XUG
Reference	CS3/ASM22003178/Rty3e2 
Loss Date	4 April 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	6 Apr 2022 11:31:44 AM
Request Date	6 April 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SLN5014L
Vehicle	
Registration #	
Make	TPVD- Nissan
Model	Latio

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages3

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

▼

▼

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2202116.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	13 April 2022

FAQ English (SG) ▾ Elaine Kuan ▾ ⋮			SUBTYPE	AUTHOR	DATE UPLOADED	
	Service Requests	⋮	Incidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	8 April 2022
	 AXA Immediate Advice _ TP - SLN 5014L.pdf.pdf		Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	8 April 2022
	 TP GIA REPORT.pdf.pdf		Reports & Statement	GIA Report	PODUVAL, Akash	6 April 2022
	 TP PRI PDF.pdf.pdf		Letters and Correspondence	Workshop	PODUVAL, Akash	6 April 2022
	 INSD GIA REPORT.pdf.pdf		Reports & Statement	GIA Report	PODUVAL, Akash	6 April 2022
	 EMAIL FROM SOLICITOR.msg.msg		Letters and Correspondence	Solicitor / Advocate	PODUVAL, Akash	6 April 2022