

ASS. REC. BY: R. Rasul

REF: CS/A1822003179/Rasul³

361K

ASSIGNMENT

From: _____ Date: _____

Veh No: SHE 365X Yr Regn: 2017 DEC

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SHE 365X

Make: TOYOTA PRIUS HYBRID 1.8 c.c. 1798

at Workshop m/s STRIDES CCMRI

Colour: MAROON A/C: Insured / Std / NI / NA

of 60, woodlands Ind PK E4

Sp. Reading: 517723 T/Radio: Insured / Std / NI / NA

Insured: AIS

Eng/No: _____

Policy No. _____

C/No: JTDKB3FU863578442

Claims No. 2022 22004418SL

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or _____

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or _____

Make of Veh: _____

Mod: Nil / S/Rim / STD A/Rim or _____

(Policy Condition)

Tyre Size: F: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-------------------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| N/S | O/S |
| <input type="checkbox"/> | <input type="checkbox"/> |

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SAILUN

Bal. or Market Value: _____

Front _____ Rear _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 6 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 6 mm

Est. Repairs: 7 days Res.: Yes or No

D.O.A. 04/04/22 D.O.I. 06/04/22

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at STRIDES

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

0/3 FRT

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|--|
| | |
| | Rasul finalised LS \$7150, 7 days. (Red \$28108.80, 80%) |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 7

1) 18/05 Typist

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) _____

Add Fee: : Site Insp (\$ _____)

Transportation:

Report Format: TP

: Interview (\$ _____)

S + RS _____ SI

Lump Sum / B.P.P. 7150

: Tech. Invs (\$ _____)

Photos

: Weekend (\$ _____)

Others

SMRT Accident Vehicle Repair Estimates

| |
|---|
| SMRT Automotive Services Pte Ltd |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592 |
| Estimator Telephone Number : 68662623 |
| Accident Reporting Number : 68662672 |

Date Generated : 06/04/2022

User ID : TuckFoo

Section A - Accident Details

| | |
|------------------------------------|-------------------------------|
| Registration Number | SHF365X |
| Case Reference Number | TAX/04/22/2012 |
| Registration Date | 12/19/2017 |
| Company Type | Strides Taxi Pte Ltd |
| Make | TOYOTA |
| Model | PRIUS4 |
| Name of Driver | LIM MUI LANG |
| Type of Accident | Others |
| Accident Date and Time | 4/4/2022 5:15 PM |
| Accident Reported Date and Time | 4/5/2022 10:57 AM |
| Insurance Surveyor Required? | Yes |
| Surveyed by | |
| Vehicle is Towed Back? | No |
| Towed Back Date and Time | |
| Replacement Vehicle issued? | No |
| Job Card Number | 24114473 |
| Special Instruction to ARC, if any | TP / FRONT PORTION/TOWED \$40 |
| Prepared Date and Time | 4/5/2022 1:04 PM |
| Chassis Number | |
| Mileage | |
| Work Shop | |
| Repair Completion Date and Time | |

Section B - Summary of Repair Estimates

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------------|---|---|
| Total Labour Cost | \$1,014.00 | \$0.00 500 |
| Total Spray Cost | \$1,314.00 | \$0.00 600 |
| Total Spare Part Cost | \$19,531.69 | \$0.00 * |
| Total Other Cost | \$696.00 | \$0.00 * |
| TOTAL COST | \$22,555.69 | \$0.00 |
| Dump Sum Total | \$22,550.00 | \$0.00 |
| Number of Repair Days | 10.0 | 5 days |
| Prepared / Adjusted By | Boon Chew Tay | Rasul |
| ARC / Surveyor Sign Off Date | 05/04/2022 1:55 PM | |
| Signature |  | ^x 4/5 Rasul 06/04/22 @ 1555M |
| Remarks | | |

Section C - Quotation and Accident Invoice Details

| | |
|------------------|----------------|
| Quotation Number | Invoice Number |
| Quotation Date | Invoice Date |
| Invoice Amount | Prepared Date |

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2022

User ID : TuckFoo

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|-------------------|-------------------------------------|
| O REPAIR FRONT PORTION | \$1,014.00 | |
| Total Labour | \$1,014.00 | 500 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| O RESPRAY FRONT BUMPER | \$378.00 | |
| O RESPRAY FRONT HOOD | \$378.00 | 200 |
| O RESPRAY FRONT SUPPORT PANEL | \$180.00 | 200 |
| O RESPRAY FRONT FENDER RH | \$378.00 | X n n |
| Total Spray Painting & Panel Beating | \$1,314.00 | 200 |

Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--|--------------------|-------------------------------------|
| OWING CHARGE | \$56.00 | |
| O WASH AND VACUUM | \$60.00 | ? receipt |
| O REPLACE SUNDRY PARTS | \$100.00 | X n n |
| O APPLY RUST-PROOFING ON AFFECTED AREA | \$120.00 | X n n |
| O CHECK WIRING AND SYSTEM FUNCTION | \$120.00 | 40 |
| O TOP UP A/C GAS | \$120.00 | 40 |
| O CONDUCT RADIATOR PRESSURE CHECK | \$120.00 | X n n |
| Total Other Costs | \$696.00 | X n n |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|----------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| | | 5370147111 | APRON SUB-ASSY, FRONT FENDER, RH | 1.00 | \$944.20 | 25.00 | \$708.15 | Replace | |
| | | 5382747050 | PROTECTOR, FR FENDER RH | 1.00 | \$90.40 | 25.00 | \$67.80 | Replace | ? |
| | | 5380747020 | SEAL SUB-ASSY, RH | 1.00 | \$50.20 | 25.00 | \$37.65 | Replace | ? |
| | | 8212347060 | WIRE, ENGINE, NO.3 | 1.00 | \$260.40 | 10.00 | \$234.36 | Replace | ? |
| | | 8531547160 | WIPER WASHER JAR | 1.00 | \$183.60 | 25.00 | \$137.70 | Replace | ? |
| | | 5321447050 | SUPPORT, RADIATOR UPPER LH | 1.00 | \$76.70 | 25.00 | \$57.53 | Replace | det |
| | | 5321347050 | SUPPORT, RADIATOR UPPER RH | 1.00 | \$76.70 | 25.00 | \$57.53 | Replace | X n n |
| | | 5320347901 | SUPPORT S/A LH | 1.00 | \$237.00 | 25.00 | \$177.75 | Replace | ? |
| | | 5320247901 | SUPPORT S/A RH | 1.00 | \$237.00 | 25.00 | \$177.75 | Replace | ? |
| | | 5320547900 | SUPPORT S/A UPPER, | 1.00 | \$364.90 | 25.00 | \$273.67 | Replace | ? |
| | | 5122847010 | FRONT PLATE, FR SUSPENSION | 1.00 | \$9.40 | 25.00 | \$7.05 | Replace | ? |
| | | 5110747020 | FRONT REINFORCEMENT SIDE RH | 1.00 | \$128.20 | 25.00 | \$96.15 | Replace | X n n |
| | | 5351047140 | LOCK ASSY, HOOD | 1.00 | \$131.10 | 25.00 | \$98.32 | Replace | ? |
| | | 5357733010 | BOLT, HOOD LOCK | 1.00 | \$10.00 | 25.00 | \$7.50 | Replace | X n n |
| | | 5253550060 | RETAINER, FR BUMPER, LH & RH | 1.00 | \$8.50 | 25.00 | \$6.38 | Replace | X n n |
| | | 5202147110 | REINFORCEMENT FRONT UPPER | 1.00 | \$691.10 | 25.00 | \$518.33 | Replace | det |
| | | 5360152010C1 | LEVER SUB-ASSY, HOOD | 1.00 | \$72.60 | 25.00 | \$54.45 | Replace | X n n |
| | | 5344047060 | SUPPORT ASSY, HOOD | 1.00 | \$41.80 | 25.00 | \$31.35 | Replace | X n n |
| | | 5342047130 | HINGE ASSY, HOOD, LH | 1.00 | \$57.00 | 25.00 | \$42.75 | Replace | X n n |

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2022

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|--|----------|-----------------|--------------|------------------|--------------------|-------------------|
| | | 5341047130 | HINGE ASSY, HOOD, RH | 1.00 | \$57.00 | 25.00 | \$42.75 | Replace | X an |
| | | 5330147110 | HOOD SUB-ASSY | 1.00 | \$938.40 | 25.00 | \$703.80 | Replace | repair |
| | | 8101647690 | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1 | 1.00 | \$486.40 | 10.00 | \$437.76 | Replace | ? |
| | | 8105647690 | COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 | 1.00 | \$486.40 | 10.00 | \$437.76 | Replace | X an |
| | | 8114547691 | UNIT, HEADLAMP, RH | 1.00 | \$2,558.90 | 10.00 | \$2,303.01 | Replace | OK |
| | | 8118547691 | UNIT, HEADLAMP, LH | 1.00 | \$2,558.90 | 10.00 | \$2,303.01 | Replace | X |
| | | 8122047020 | LAMP ASSY, FOG, LH | 1.00 | \$910.20 | 10.00 | \$819.18 | Replace | OK |
| | | 5210347010 | EXTENSION SUB-ASSY, LH | 1.00 | \$116.30 | 25.00 | \$87.23 | Replace | X an |
| | | 5210247020 | EXTENSION SUB-ASSY, RH | 1.00 | \$116.30 | 25.00 | \$87.23 | Replace | X an |
| | | 5213247010 | REINFORCEMENT FRONT LOWER | 1.00 | \$238.50 | 25.00 | \$178.88 | Replace | ? |
| | | 5261847090 | ABSORBER, FR BUMPER LOWER | 1.00 | \$117.00 | 25.00 | \$87.75 | Replace | X an |
| | | 5339547040 | SEAL, HOOD TO FR END | 1.00 | \$24.40 | 25.00 | \$18.30 | Replace | X an |
| | | 5216116010 | CLIPS PIECE, FRT & RR BUMPER | 10.00 | \$1.50 | 25.00 | \$11.25 | Replace | X an |
| | | 5144747030 | COVER, ENGINE UNDER CENTER | 1.00 | \$94.50 | 25.00 | \$70.88 | Replace | OK |
| | | 5144347020 | COVER, ENGINE UNDER SIDE RH | 1.00 | \$76.90 | 25.00 | \$57.68 | Replace | ? |
| | | 5144447010 | COVER, ENGINE UNDER SIDE LH | 1.00 | \$76.90 | 25.00 | \$57.68 | Replace | ? |
| | | 5144247030 | COVER, ENGINE UNDER, REAR | 1.00 | \$36.50 | 25.00 | \$27.38 | Replace | X |
| | | 8121047020 | LAMP ASSY, FOG, RH | 1.00 | \$910.20 | 10.00 | \$819.18 | Replace | X |
| | | 5211547050 | SUPPORT, FR BUMPER RH | 1.00 | \$76.90 | 25.00 | \$57.68 | Replace | OK |
| | | 5211647050 | SUPPORT, FR BUMPER LH | 1.00 | \$82.30 | 25.00 | \$61.72 | Replace | ? |
| | | 5212747907 | COVER, FR BUMPER RH | 1.00 | \$28.10 | 25.00 | \$21.08 | Replace | X an |
| | | 5212847906 | COVER, FR BUMPER LH | 1.00 | \$28.10 | 25.00 | \$21.08 | Replace | X an |
| | | 5211447190 | BRACKET, FR BUMPER | 1.00 | \$99.80 | 25.00 | \$74.85 | Replace | X an |
| | | 5321747030 | BRACE, HOOD LOCK SUPPORT | 1.00 | \$76.20 | 25.00 | \$57.15 | Replace | ? |
| | | 5110847020 | FRONT REINFORCEMENT SIDE LH | 1.00 | \$129.30 | 25.00 | \$96.98 | Replace | X an |
| | | 5302847010 | SUPPORT SUB-ASSY LOWER | 1.00 | \$397.40 | 25.00 | \$298.05 | Replace | ? |
| | | 8531947170 | WIPER WASHER INLET | 1.00 | \$55.40 | 25.00 | \$41.55 | Replace | X an |
| | | 85330-58010 | MOTOR AND PUMP ASSY, WINDSHIELD WASHER | 1.00 | \$245.00 | 10.00 | \$220.50 | Replace | X an |
| | | 1659237020 | GUIDE, RADIATOR AIR | 1.00 | \$93.90 | 25.00 | \$70.43 | Replace | X an |
| | | 5315547010 | SEAL, RADIATOR GRILLE | 2.00 | \$40.70 | 25.00 | \$61.05 | Replace | X an |
| | | 1640037310 | RADIATOR ASSY | 1.00 | \$1,841.10 | 25.00 | \$1,380.82 | Replace | ? |
| | | 1636137070 | FAN RADIATOR, RH | 1.00 | \$233.00 | 25.00 | \$174.75 | Replace | X an |
| | | 1636137060 | FAN RADIATOR, LH | 1.00 | \$181.80 | 25.00 | \$136.35 | Replace | X an |
| | | 1671137160 | FAN SHROUD RADIATOR | 1.00 | \$219.30 | 25.00 | \$164.48 | Replace | X an |
| | | 1636336160 | MOTOR, COOLING FAN, RH | 1.00 | \$443.40 | 10.00 | \$399.06 | Replace | X an |
| | | 1636337060 | MOTOR, COOLING FAN, LH | 1.00 | \$543.50 | 10.00 | \$489.15 | Replace | X an |
| | | 8846010320 | AIR CON CONDENSER ASSY | 1.00 | \$1,317.70 | 25.00 | \$988.28 | Replace | X an |

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/04/2022

User ID : TuckFoo

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|-------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| | | 8211147J21 | WIRE, ENGINE ROOM MAIN | 1.00 | \$6,138.00 | 10.00 | \$5,524.20 | Replace | X n n |
| | | 821H247010 | WIRE, AIR CONDITIONER | 1.00 | \$445.70 | 10.00 | \$401.13 | Replace | X n n |
| | | 5380147080 | FENDER SUB-ASSY, FR, RH | 1.00 | \$933.10 | 25.00 | \$699.83 | Replace | bt / |
| | | 7537447140 | EMBLEM, SIDE PANEL (HYBRID) | 1.00 | \$52.90 | 25.00 | \$39.68 | Replace | na / |
| | | 5387547070 | LINER, FR FENDER, RH | 1.00 | \$198.40 | 25.00 | \$148.80 | Replace | cut / |
| | | 5385147061 | PAD, FR WHEEL RH | 1.00 | \$57.70 | 25.00 | \$43.28 | Replace | na / |
| | | | NUMBER PLATE FRAME | 1.00 | \$25.00 | 0.00 | \$25.00 | Replace | scr / |
| | | 5261147140 | ABSORBER, FR BUMPER | 1.00 | \$70.30 | 25.00 | \$52.72 | Replace | ca / |
| | | 7531047060 | EMBLEM ASSY FRONT | 1.00 | \$87.10 | 25.00 | \$65.32 | Replace | na / |
| | | 5310147080 | GRILLE SUB-ASSY | 1.00 | \$335.60 | 25.00 | \$251.70 | Replace | de / |
| | | 5142047030 | COVER ASSY, ENGINE | 1.00 | \$180.10 | 25.00 | \$135.08 | Replace | ? |
| | | 5141047020 | COVER ASSY, ENGINE UNDER CENTER SET | 1.00 | \$452.80 | 25.00 | \$339.60 | Replace | ? |
| | | | NUMBER PLATE | 1.00 | \$35.00 | 0.00 | \$35.00 | Replace | by sub / |
| | | 5311247240 | GRILLE, RADIATOR | 1.00 | \$165.00 | 25.00 | \$123.75 | Replace | ca / |
| | | 5211947962 | COVER, FR BUMPER | 1.00 | \$495.50 | 25.00 | \$371.63 | Replace | TURN / |
| total | | | | | \$29,281.10 | | \$24,414.61 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| total | | | | | | | | | |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 05/04/2022 14:23 (SGT)
Date of Accident 04/04/2022 17:15 (SGT)
Exact Location of Accident 538 Bedok North Street 3, Singapore 460538
Additional Location Information BLK 538 BEDOK NORTH STREET 3
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHF365X

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Strides Taxi Pte Ltd
Company Reg No 1XXXXX369K
Email Address AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No (Phone) +65-68662671
Alternative Phone No (Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1800

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number D-22099115MFSH
Cover Note Number -

DRIVER

Name of Driver LIM MUI LANG
NRIC No SXXXX416B

| | |
|--|----------------------------|
| Date Of Birth | 25/11/1959 |
| Occupation | Outdoor |
| Date Of Driving Pass | 29/01/1992 |
| Driving experience | 30 YEARS AND 3 MONTHS |
| Gender | Female |
| Mobile Number | |
| Alt. Phone Number | (Phone) +65-68662672 |
| Email Address | - |
| Address | AUTO-SVCS-TARC@SMRT.COM.SG |
| Address complement | 11 |
| Postcode | - |
| Is the driver the policyholder? | - |
| If No, Relationship of the Driver with the Insured | No |
| Does Driver Own Other Vehicles? | RELIEF |
| Vehicle Registration Number of Other Vehicle Owned by Driver | No |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|---|
| Type of Accident | Hit and run / Vandalism / Damaged whilst parked |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 0 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

I PARKED MY TAXI IN THE CAR PARK OF BLK 538 BEDOK NORTH STREET 3 AND WENT TO RUN AN ERRAND. WHEN I CAME BACK TO MY TAXI WITH MY HIRER, THE FRONT BUMPER WAS DISLODGED AND WAS ON THE GROUND. I CALLED THE POLICE FOR ASSISTANCE. WHILST I WAS TALKING TO THE POLICE, A VEHICLE GBL748P APPEARED.. ACCORDING TO THE MANAGER THE DRIVER WAS IN A SHOCK AND DID NOT KNOW WHAT TO DO. THIRD PARTY'S MANAGER GAVE ME HIS NAME CARD AND WANTED MY COMPANY TO CONTACT HIM.

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | GBL748P |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Commercial vehicle |
| Name of Driver | VELAYUTHAM MARIMUTHU |

Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**
6. The report will be forwarded by the insurers of the **GIA Records Management Centre** established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

[Handwritten Signature]

5/4/22

Driver's Signature (if driver is not the policyholder) / Date & Time

[Handwritten Signature]

5.4.2022

Witnessed by Reporting Centre Personnel

Sketch Plan

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------|--------------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 369K |
| Vehicle No.: | SHF365X |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 07 Apr 2022 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | PRIUS HYBRID 1.8 CVT |
| Primary Colour: | Maroon |
| Manufacturing Year: | 2017 |
| Engine No.: | 2ZR8276171 |
| Chassis No.: | JTDKB3FU803578442 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | \$29,007.00 |
| Original Registration Date: | 19 Dec 2017 |
| First Registration Date: | 19 Dec 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,000.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 18 Dec 2025 |
| PARF Rebate Amount: | \$3,750.00 |
| COE Expiry Date: | 18 Dec 2025 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$34,159.00 |
| COE Rebate Amount: | \$15,782.00 |
| Total Rebate Amount: | \$19,532.00 |

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Apr 2022

OK