

SAS-KIV

COMFORTDELGRO ENGINEERING PTE LTD

Date: 05.04.2022

TS

REPAIR ESTIMATE

Time: 08:46:52

Page: 1/2

LKK-

(NTUC-LIS)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305511403
REGN NO : SHD4509H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 19.12.2019
DATE/TIME IN : 04.04.2022 12:30
ACCIDENT DATE : 04.04.2022

19/12
me Move
30
c.c. LIS
d / Stc
1 / Stc

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2538-G WING MIRROR RH 1 1,391.70 20.00 1,113.36
0002 28-01-9999-2023-A REAR DOOR APPS RH 1 80.00 10.00 72.00

cr / cra
/ nec

SUB-TOTAL : 1,185.36

JOB NATURE

0000 PB PANEL BEATING-Rear Fender RH 800.00
0001 SP SPRAYPAINT-Frt WRC Piilar RH 1200.00
0002 17-01 CHECK ALL WIRINGS. 50.00
0003 20-00 TUFF COAT ON AFFECTED PARTS. 30.00
0004 20-05 Rear Door Adv.Sticker RH 100.00
0005 20-05 Rear Fender Adv.Sticker RH 100.00
0006 23-01 TOWING FEE 0.00

350
900
30
30
/ nec
/ nec

SUB-TOTAL : 2,280.00

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: