



Your Ref: S1M03M28

Date: 18th May 2022

Our Ref: CS3/ASM21011610/Tty3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Ang Yvonne

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKA 154D

INSURED VEHICLE: SHA 8646J

ACCIDENT DATE: 12/11/2021

We thank you for your instruction on 06/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKA 154D from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement of Vehicles SKA 154D and SHA 8646J.
- c) Police Report of Vehicles SKA 154D.
- d) Final Repair Bill of SKA 154D from M/s Garage 13 Pte Ltd.
- e) Colour damaged vehicle photographs of SKA 154D.

Pre-Repair Inspection Date : 15/11/2021 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKA 154D
Make & Model	: Volkswagen New Golf 1.4 TSI AT 5K14Q5
Year of Registration	: 2011
Chassis Number	: WVWZZZ1KZBW111137
Engine Capacity	: 1390 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.