

ASS. REC. BY: TLim

REF:

cc 4/AIC 22003203/Bpa3H8100 Dong

ASSIGNMENT

From: _____ Date: 7/4/2022

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGW 52458at Workshop m/s Dean Autoproof 160 Sin Hung Dr # 01-14

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 36,000/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRSW

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGW 52458Yr Regn: 23/7/2007Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Corolla Altis

c.c. _____

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 197 102

T/Radio: Insured / Std / NI / NA

Eng/No: 3824676703C/No: MR0538EC107151252Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ SRim / STD A/Rim orTyre Size: F: 185/70/14R: 185/70/14BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 31/3/2022D.O.I. 7/4/2022Survey held at Dean AutoproDes. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range <u>5,000/-</u> - <u>6,000/-</u>
	Recommended CR: LS <u>\$5,050/-</u> <u>TLim</u> <u>13/4/2022</u>
	MV <u>36,000/-</u> <u>TLim</u>
	PV <u>25,577/-</u> <u>7/4/2022</u>
	NV <u>10,423/-</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Rep. Format: _____

Lump Sum / L.B.I. / _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SGW 5245 Z**
 Model : Toyota Altis
 Year : 2007
 Chassis No : MR053ZEC107151252

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front door RH	1	\$ 927.00	\$ 927.00
2	Front door black tape	1	\$ 85.00	\$ 85.00
3	Front door protector RH	1	\$ 358.00	\$ 358.00
4	Rear door RH	1	\$ 915.70	\$ 915.70
5	Rear door black tape	1	\$ 85.00	\$ 85.00
6	Rear door protector RH	1	\$ 358.00	\$ 358.00
7	Rear door outer handle	1	\$ 350.00	\$ 350.00
8	Rear door weatherstrip	1	\$ 215.00	\$ 215.00
9	Rear door inner lock	1	\$ 415.00	\$ 415.00
10	Rear door inner lock striker	1	\$ 48.00	\$ 48.00
11	Rear door inner trimboard	1	\$ 542.00	\$ 542.00
12	Rear door glass regulator	1	\$ 356.00	\$ 356.00
13	Rear door glass regulator motor	1	\$ 750.00	\$ 750.00
14	Rear door glass channel bracket	1	\$ 185.00	\$ 185.00
15	Rear door hinge	2	\$ 115.00	\$ 230.00
16	Rocker panel RH	1	\$ 789.00	\$ 789.00
17	Rear fender RH	1	\$ 845.80	\$ 845.80
18	Rear fender inner cowling RH	1	\$ 87.00	\$ 87.00
19	Rear windscreen moulding	1	\$ 241.60	\$ 241.60
20	Rear bumper	1	\$ 782.40	\$ 782.40
21	Rear shock absorber RH	1	\$ 499.30	\$ 499.30
22	Rear axle	1	\$ 1,088.00	\$ 1,088.00
23	Rear wheel hub with bearing RH	1	\$ 452.00	\$ 452.00
Parts Sub Total :				\$ 4716.10 10,604.80
Discount 25% :				\$ 1190.25 2,651.20
PARTS TOTAL :				\$ 7,953.60

3537.08

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Front door sealant	1	\$ 100.00	\$ 100.00
3	Front door protector clips	1	\$ 50.00	\$ 50.00
4	Rear door sealant	1	\$ 100.00	\$ 100.00 30.00
5	Rear door inner trimboard clips	1	\$ 50.00	\$ 50.00 30.00
6	Rear door protector clips	1	\$ 50.00	\$ 50.00
7	Rocker panel sealant	1	\$ 100.00	\$ 100.00
8	Rear fender sealant	1	\$ 100.00	\$ 100.00
9	Rear fender inner cowling clips	1	\$ 50.00	\$ 50.00
10	Rear windscreen sealant	1	\$ 100.00	\$ 100.00 40.00
11	Rear windscreen inner seal	1	\$ 80.00	\$ 80.00
12	Rear windscreen primer & cleaner	1	\$ 60.00	\$ 60.00
13	Rear bumper clips	1	\$ 50.00	\$ 50.00 30.00
14	Rear bumper side retainer	2	\$ 67.00 73.90	\$ 147.80 134.00
15	Rear alloy rim RH <i>Chrome</i>	1	\$ 980.00	\$ 980.00 250.00
16	Rear tyre RH	1	\$ 480.00	\$ 480.00
SPECIAL NETT TOTAL :				\$ 2,577.80

484.00

Nos.	LABOUR	S\$
1	R&R front door component	\$ 150.00
2	R&R rear door component	\$ 150.00 80.00
3	R&R rear reverse sensor	\$ 150.00 60.00
4	R&R rear under carriage	\$ 300.00 120.00
5	R&R rear tyre and balancing	\$ 100.00 30.00
6	Wheel alignment	\$ 180.00 60.00
7	Check wiring	\$ 100.00
8	Upholstery	\$ 300.00
9	Panel beating	\$ 1800.00 1200.00
10	Rust proofing	\$ 200.00
11	Spray painting	\$ 1800.00 800.00
LABOUR TOTAL :		\$ 5,230.00

Survey 7/4/2022
Resurvey 8/4/2022
1400hrs
1345hrs
Lump sum repair
Repair days 9

PARTS TOTAL : \$ 7,953.60

SPECIAL NETT TOTAL : \$ 2,577.80

LABOUR TOTAL : \$ 5,230.00

GRAND TOTAL : \$ 15,761.40

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LS 5050/y

TGlin Mr
13/4/2022

Parts 3537.00
SN 484.00
Labour 2350.00
6371.08
@20% 1274.22
5096.86

Condition (COS)

(01)Item (2)Denied (3)Disowned (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shilled (09)Duckled (10)Broken (11)Necessary (12)Missing
(13)Turn (14)Unconfirmed (15)Not Working

MOTOR CAR (RH)

ACTION/AC

(1)Replace (✓) (2)Repair (X) (3)Check (✓)
(4)Not Consistent (NC)

Aug 2015

Vehicle No: SGW 5245 Z

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door	DD	✓	
1351	993284	Rear RH Door Protector	WT	✓	
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding	BT	✓	
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator	BT	✓	
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber <i>weatherstrip</i>	TN	✓	
1360	993276	Rear RH Door Outer Handle	WT	✓	
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock	JM	✓	
1363	993256	Rear RH Door Inner Trim Board	BR	✓	
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
994070		Roof Top Panel			
994098		Roof Top Moulding			
994085		Roof Top Air-bag			
994084		Roof Top Air-bag Sensor			
994083		Roof Top Air-bag Control Unit			
992958		Rear Bumper	CRA	✓	
992976		Rear Bumper Bracket			
993068		Rear Bumper Side Retainer			
993045		Rear Bumper Reinforcement			
993077		Rear Bumper Sponge			
993040		Rear Bumper Protector			
993026		Rear Bumper Moulding			
993023		Rear Bumper Lower Spoiler			
995116		Rear RH Taillamp			
993456		Rear RH Fender	DD	✓	
993450		Rear RH Fender Protector			
990247		Sticker			
		Rear <i>door black tape</i>	NEL	✓	
		<i>Rocker panel RH</i>	DD	✓	
		<i>rear window screen moulding</i>	NEL	✓	
		<i>rear wheel hub bearings</i>	JM	✓	
		<i>rear alloy rim chrome</i>	WT	✓	

No of Items: 15

Assessor: TCum

13/4/2022

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	067R
Vehicle Details	
Vehicle No.:	SGW5245Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	3ZZ4676703
Chassis No.:	MR053ZEC107151252
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,924.00
Original Registration Date:	23 Jul 2007
First Registration Date:	23 Jul 2007
Transfer Count:	0
Actual ARF Paid:	\$16,417.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$48,200.00
COE Rebate Amount:	\$25,577.00
Total Rebate Amount:	\$25,577.00

The information contained herein is correct as at 01 Apr 2022

OK

MV 36,000/2
PV 25,577/2
NV 10,423/2

Tellin Lim
7/4/2022



Posted: 11-Apr-2022



Toyota Corolla Altis 1.6A (COE \$14,000 \$9,590 /yr 29-Sep-2008 1,598 cc 245,600 km Sedan Available till 09/2023)

Stock Condition. Regular Maintenance. Well Taken Care. View To Believe. Accident Free. Inspection Welcome. Attractive Financing Rates, High Loan, Trade In, Consignment Options Available. Any Queries Please Feel Free To Contact Us. By Appointment Only. Price Negotiable.

Posted: 01-Apr-2022



Toyota Corolla Altis 1.6A (COE \$45,588 \$7,070 /yr 24-Sep-2008 1,598 cc 178,244 km Sedan Available till 09/2028)

We are the COE specialists, no gimmicks, honest dealing, immaculate condition, wear and tear all replaced with receipts, road tax till 09/2022, cheapest Altis in the market, bank or full loan available! Easy approval. High trade in offer or consignment options available. ST...

PREMIUM AD

Posted: 04-Apr-2022



Toyota Corolla Altis 1.6A (COE \$14,900 \$10,830 /yr 29-Aug-2008 1,598 cc 150,000 km Sedan Available till 08/2023)

Best Value For Your Money. Direct Owner's Very Beautiful Blue Toyota Corolla Altis 1.6 Auto. A Well Maintained, Service Regularly And Well Taken Care By Owner. Original Condition, Genuine Mileage And Well Kept. Trade In, Bank Loan, In House Loan Available. Don't Miss It! C...

Posted: 13-Mar-2022

ADVERTISING



Toyota Corolla Altis 1.6A (COE \$45,800 \$7,330 /yr 11-Jul-2008 1,598 cc - Sedan Available till 07/2028)

Loan up to 100% available, overall guarantee cheaper than renting a car! Very good condition and fuel efficient! Trade In welcomed, WhatsApp me now!

PREMIUM AD

Monster Motors Pte Ltd

Posted: 02-Apr-2022



Toyota Corolla Altis 1.6A (COE \$54,800 \$8,950 /yr 28-May-2008 1,598 cc - Sedan Available till 04/2028)

\$0 Down And Full Loan Available. 100% Approval. Car Fr \$500/Month Only. Bad Credit And Discharged Bankruptcy Accepted. All Cars With Warranty. We Have Interest From 1.88%. Open Daily Till 11pm Including Sunday And PH. Call/Whatsapp To Set Appointment. Onli...

Posted: 24-Feb-2022



Toyota Corolla Altis 1.6A (COE \$49,800 \$8,280 /yr 17-Apr-2008 1,598 cc 69,000 km Sedan Available till 04/2028)

Rare 1 Owner Unit! One Of The Most Reliable And Fuel Efficient Mid Size Sedan. Well Maintained By Previous Owner! Flexible Finance Option Available To Suit Your Needs. Trade In Available. Call Us Now To Make An Appointment Now!

Posted: 09-Apr-2022



Toyota Corolla Altis 1.6A (COE \$49,800 \$8,290 /yr 15-Apr-2008 1,598 cc - Sedan Available till 04/2028)

Rare 1 owner Unit! Full loan in house interest rates from 3.xx%, monthly installment at \$9xx. Bank loan rates from 2.88% only! In house warranty provided, perfect condition with no repairs needed! All vehicles undergone workshop 120 point inspection check to be certified...

PREMIUM AD

Precise Auto Trading Pte Ltd

Posted: 04-Apr-2022



Toyota Corolla Altis 1.6A (COE \$10,800 \$10,980 /yr 08-Apr-2008 1,598 cc 272,000 km Sedan Available till 04/2023)

PREMIUM AD

2022

Compare

R020184
8.4.22 9:22
SGW5245Z
TEAM



SGW5245Z

Factory Japan 2022.0.1 : Toyota : Corolla / Sprinter : E120 Series : NZE121G
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-1°05'	-1°05'	-1°15' 0°15'
6°26'	6°26'	2°00' 3°30'
-0°05'	-0°05'	-0°06' 0°06'
10°58'	10°58'	10°30' 12°00'
9°53'	9°53'	9°15' 12°15'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°39'	-0°39'	-1°15' 0°15'
6°26'	6°26'	2°00' 3°30'
0°14'	0°14'	-0°06' 0°06'
11°02'	11°02'	10°30' 12°00'
10°23'	10°23'	9°15' 12°15'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°26'	-0°26'	-0°45' 0°45'
0°01'	0°01'	-0°45' 0°45'
-0°04'	-0°04'	
0°10'	0°10'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-1°40'	-1°40'	-2°00' -1°00'
0°05'	0°05'	-0°01' 0°13'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°44'	-2°44'	-2°00' -1°00'
-0°30'	-0°30'	-0°01' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
1°04'	1°04'	-0°30' 0°30'
-0°24'	-0°24'	-0°03' 0°25'
0°17'	0°17'	
0mm	0mm	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	31/03/2022 17:16 (SGT)
Date of Accident	31/03/2022 00:10 (SGT)
Exact Location of Accident	Geylang Rd, Singapore
Additional Location Information	Turning into Geylang Lorong 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGW5245Z

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Unique Tourist Service Pte Ltd
Company Reg No	197401067R
Email Address	unigtour@singnet.com.sg
Mobile Phone No	(Phone) +65-62927656
Alternative Phone No	(Office) +65-62927656

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	999993578/100734081-00000
Cover Note Number	-

DRIVER

Name of Driver	Toh Hock Lye
NRIC No	S7335078F

Date Of Birth	20/09/1973
Occupation	Indoor
Date Of Driving Pass	10/12/1991
Driving experience	30 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94855133
Alt. Phone Number	-
Email Address	RT20091973@gmail.com
Address	Blk 120 Pending Road #05-174
Address complement	-
Postcode	670120
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Wong Kum Fatt
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SND6530K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**




I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 Policyholder's Signature / Date & Time 31 MAR 2022	 Driver's Signature (If driver is not the policyholder) / Date & Time 31 MAR 2022	 Witnessed by Reporting Centre Personnel Angie Soh
--	--	---

Sketch Plan



Describe Circumstances of the Accident


ON 31ST MARCH 2022 AT ABOUT 0010HRS. I WAS DRIVING
ON GELANG ROAD TURNING RIGHT TO LORONG 1, GELANG


I WAS ON 2ND LANE FROM THE RIGHT WHICH ALLOW
RIGHT TURN AND GOING STRAIGHT.


WHEN THE TRAFFIC LIGHT TURNED GREEN, I PROCEED TO
MAKE RIGHT TURN, THE CAR ON MY RIGHT APPARENTLY
WAS GOING STRAIGHT ON THE WRONG LANE AND HIT
ONTO MY REAR RIGHT PORTION

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date
Time 31 MAR 2022


Driver's Signature (if driver is not the policyholder) / Date
& Time 31 MAR 2022


Witnessed by Reporting Centre
Personnel
Angie Soh